



## Public Service Company <sup>of</sup> Colorado

16805 Weld County Road 19 1/2, Platteville, Colorado 80651

December 6, 1979  
Fort St. Vrain  
Unit No. 1  
P-79295

Mr. Karl V. Seyfrit, Director  
Nuclear Regulatory Commission  
Region IV  
Office of Inspection and Enforcement  
611 Ryan Plaza Drive  
Suite 1000  
Arlington, Texas 76012

REF: Facility Operating License  
No. DPR-34


Docket No. 50-267

Dear Mr. Seyfrit:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/79-59, Final, submitted per the requirements of Technical Specification AC 7.5.2(b)2.

Also, please find enclosed one copy of the Licensee Event Report for Reportable Occurrence Report No. 50-267/79-59.

Very truly yours,

  
Don Warembourg  
Manager, Nuclear Production

DW/clb

cc: Director, MIPC

1542 152

4002  
S  
1/1

79121 20 338

REPORT DATE: December 6, 1979

REPORTABLE OCCURRENCE 79-59

OCCURRENCE DATE: November 9, 1979

ISSUE 0

Page 1 of 3

FORT ST. VRAIN NUCLEAR GENERATING STATION  
PUBLIC SERVICE COMPANY OF COLORADO  
16805 WELD COUNTY ROAD 19 1/2  
PLATTEVILLE, COLORADO 80651

REPORT NO. 50-267/79-59/03-L-0

Final

IDENTIFICATION OF  
OCCURRENCE:

On November 9, 1979, with the reactor in a shutdown condition, engineering personnel observed that boiler feed snubber BFS-412 was inoperable.

Since the reactor had been operated at power during the surveillance interval, this constitutes operation in a degraded mode of LCO 4.3.10, and is reportable per Fort St. Vrain Technical Specification AC 7.5.2(b)2.

EVENT  
DESCRIPTION:

On November 9, 1979, with the reactor shutdown for scheduled maintenance, engineering personnel observed that the oil reservoir for boiler feed snubber BFS-412 was empty. See details of Figure 1.

Because the oil reservoir was empty, this snubber was determined to be inoperable. This snubber had been verified operable during performance of the previous surveillance.

CAUSE  
DESCRIPTION:

Reason for snubber being inoperable was an empty hydraulic oil reservoir.

CORRECTIVE  
ACTION:

The snubber hydraulic oil reservoir was refilled and the snubber returned to service. The present surveillance interval is 124 days  $\pm$  25%. No change is required as a result of this occurrence.

No further corrective action is anticipated or required.

1542 153

POOR ORIGINAL

figs. 200, 201




FIGURE 1

1542 154

Prepared by: Cathy C. Hirsch  
Cathy C. Hirsch  
Technical Services Technician

Reviewed by: J. W. Gahm  
J. W. Gahm  
Technical Services Supervisor

Reviewed by: Frank M. Mathie  
Frank M. Mathie  
Operations Manager

Approved by: Don Warembourg  
Don Warembourg  
Manager, Nuclear Production

1542 155