

**LICENSEE EVENT REPORT**

CONTROL BLOCK: 

--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

5	1	G	A	E	I	H	2	2	0	0	0	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4			5	
8	9	LICENSEE CODE						14	15	LICENSE NUMBER											25	LICENSE TYPE					30	37	CAT	58

REPORT SOURCE L 6 0 5 0 0 0 3 6 6 7 0 9 2 6 7 9 3 1 0 1 9 7 9 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While performing routine surveillance procedure, HNP-2-3002, High Drywell Pressure

0 3 | Functional Test and Calibration, instruments 2C71-N002A, C and D were found to exceed

0 4 | the Tech Spec limit of less than or equal to 2 psig. All switches actuated at a

0 5 | pressure of less than or equal to 2.16 psig. There was no effect on the environs.

0 6 | There have been no similar occurrences on these instruments.

0 7 |

0 8 |

3 9		SYSTEM CODE I A (11)		CAUSE CODE E (12)		CAUSE SUBCODE E (13)		COMPONENT CODE I N S T R U (14)				COMP. SUBCODE S (15)		VALVE SUBCODE Z (16)	
8		9 10		11		12		13 14 15 16 17 18				19		20	
17		EVENT YEAR 7 9		SEQUENTIAL REPORT NO. 1 0 8		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0					
21 22		23		24 25 26		27		28 29		30		31		32	
ACTION TAKEN E (18)		FUTURE ACTION G (19)		EFFECT ON PLANT Z (20)		SHUTDOWN METHOD Z (21)		HOURS 0 0 0 0 (22)		ATTACHMENT SUBMITTED Y (23)		NPRO-4 FORM SUB. N (24)		PRIME COMP. SUPPLIER N (25)	
33		34		35		36		37 38 39 40		41		42		43	
44		45		46		47		48 49 50 51		52		53		54	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

11 0 The cause was contributed to setpoint drift. The instruments were recalibrated and  
11 1 returned to service. Investigations were made into reasons that may have caused a  
11 2 multiple drift. A possible item, which we believe contributed to the multiple drift.  
11 3 was the test equipment specified by HNP-2-3002 would allow the use of pressure  
11 4 instrumentation with lesser resolution than should be used on this application. (cont.)

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	E	28	0	9	6	29	NA	44
								B	31
								Surveillance test	

ACTIVITY		CONTENT		RELEASED		OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
11	6	2	33	2	34	NA		NA		NA	

PERSONNEL INJURIES  
NUMBER DESCRIPTION (41)

1 4 0 0 0 45 NA

LOSS OF OR DAMAGE TO FACILITY		(43)			1221 095
TYPE	DESCRIPTION				
2	(12)		NA		

10  
PUBLICITY  
ISSUED DESCRIPTION (45)  
NRC USE ONLY  
10290276

2 0 N 44 NA 7910230 68 69 012 267 7791

NAME OF PREPARER R. T. Nix

PHONE: 912-367-7781

NRC USE ONLY



Georgia Power Company  
Plant E. I. Hatch  
Baxley, Georgia 31513

Reportable Occurrence Reprot No. 50-366/1979-108

Cause Description and Corrective Actions (cont)

The procedure was revised to state explicitly what instrumentation should be used. No other factors were found which would contribute to multiple drift.

1221 096