

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK:

--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	G A E I H 1												2	0	0	0	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4			5			
8		LICENSEE CODE												14	LICENSE NUMBER												25	LICENSE TYPE					30	57 CAT 58				

REPORT SOURCE L 6 0 5 0 0 0 3 2 1 7 1 0 1 3 7 9 8 1 0 2 5 7 9 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While performing HNP-1-3410, RCIC Steam Line Flow Functional Test and Calibration, at

0 3 steady state power operation, instrument 1E51-N017 switch contacts No. 2 failed to

0 4 actuate within Tech Specs limits ($\leq +182 + 16$ in. H_2O head correction). The switch

0 5 actuated at 219 in. H_2O . There was no effect on safe plant operation since instrument

0 6 1E51-N018 was operating and available for the same function. This is a re-occurring

0 7 problem as reported on LER 77-98.

08		789		09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE		789			
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	
09		78		9		10		11		12		13				14		15		16		80	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS	
110	Instrument malfunction was attributed to instrument drift. 1E51-N017 was calibrated
111	per HNP-1-5202 and set to the correct setpoint. Functional Test and Calibration
112	Procedure HNP-1-3410 was performed and completed satisfactorily.

8 9
FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
1 5 E (28) 0 9 8 (29) NA B (31) Normal Surveillance Testing

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)
1 6 Z (33) Z (34) NA

LOCATION OF RELEASE (36)
NA

PERSONNEL EXPOSURES			TYPE		DESCRIPTION
NUMBER					
1	7	0	0	0	NA

PERSONNEL INJURIES			DESCRIPTION		NA	
NUMBER						
0	0	0	(40)			

7	8	9	11	12	
LOSS OF OR DAMAGE TO FACILITY					(43)
TYPE DESCRIPTION					
1	9	Z	(42)		MA

7 8 9 10
PUBLICATION
ISSUED DESCRIPTION (45) 7911010490 NA
(2) (0) (N) (44) NRC USE ONLY

NAME OF PREPARER R. T. Nix

PHONE: 912-367-7781