

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	J	A	F	1	2	0	0	-	0	0	0	0	-	0	0	0	3	4	1	1	1	1	4			5	
7	8	LICENCEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	3	3	7	1	0	0	2	7	9	8	1	0	3	0	7	9	9
60	61	DOCKET NUMBER						68	69	EVENT DATE						74	75	REPORT DATE						80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2	See Attachment
---	---	----------------

0	3	
---	---	--

0	4	
---	---	--

0	5
---	---

0	6
---	---

0	7	
---	---	--

0	8	
---	---	--

7 8 9 10 11 12 13 14 15 16 17 18 19 20
 0 9 I B E E I N S T R U S Z

(17) LER RO REPORT NUMBER
 SEQUENTIAL REPORT NO.
 OCCURRENCE CODE
 REPORT TYPE
 REVISION NO.

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER					
E	18	X	19	Z	20	Z	21	0	0	0	0	22	Y	23	Y	24	N	25	Y	0	1	0	26
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	See Attachment
---	---	----------------

1 1 | _____

1	2
---	---

1	3	
---	---	--

1	4
---	---

FACILITY STATUS (28) 1 5 E
 % POWER 0 8 7 (29)
 OTHER STATUS (30) NA
 METHOD OF DISCOVERY (31) B
 DISCOVERY DESCRIPTION (32) Surveillance Test

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z (33) (34) NA

7 8 9 10 11

AMOUNT OF ACTIVITY (35)

NA

45

LOCATION OF RELEASE (36)

8

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37) Z	(38) NA	(39)		

PERSONNEL INJURIES	
NUMBER	DESCRIPTION
1 8 0 0 0	41 NA

1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5															

8 9 10
PUBLICITY
ISSUED DESCRIPTION (45) 7911020 300 NRC USE ONLY
2 0 N (44) NA

NAME OF PREPARER W. Verne Childs

PHONE: (315) 342-3840

POWER AUTHORITY OF THE STATE OF NEW YORK
JAMES A. FITZPATRICK NUCLEAR POWER PLANT

DOCKET NO. 50-333

ATTACHMENT TO LER 79-078/03L-0

Page 1 of 1

During normal operation and while performing Instrument Surveillance Procedure F-ISP-3-2, titled "Reactor Low Low/Low Low Water Level," reactor water level instrument 02-3-LIS-72A was found out of calibration in the non-conservative direction. This surveillance was being conducted to satisfy the requirements of Technical Specifications, Appendix A, Table 3.2-2 and the switch was found set at approximately 60 inches compared to a Technical Specification requirement of equal to or greater than -38 inches.

The other three switches associated with the same parameter were immediately verified operable and within calibration and the out of calibration level switch was placed in the trip condition. Therefore, the event did not represent a significant hazard to the public health and safety.

Surveillance tests conducted on this instrument are normally performed on a monthly basis. Since the precise cause of the instrument drift is not known, a surveillance frequency has been increased to daily until the switch may be replaced or until the results of surveillance demonstrate that the instrument is stable and reliable. When this determination has been made, a followup report will be submitted.

1249 120