

CONTROL BLOCK: 

						(1)
--	--	--	--	--	--	-----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	C	T	M	N	S	2	2	0	0	-	0	0	0	0	-	0	0	0	3	4	1	1	1	1	4			5				
7	8	9					14	15											25	26						30	57	CAT	58				
		LICENSEE CODE						LICENSE NUMBER																		LICENSE TYPE							

CON'T

0 1  
7 8

REPORT SOURCE L 6 0 5 0 0 0 3 3 6 7 0 8 0 3 7 9 8 1 1 0 1 7 9 9  
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

During steady state power operation, the seismic bracing for various cells in the 201A and B batteries was removed to allow for cell inspection and/or replacement. This resulted in the batteries being declared inoperable in accordance with Section 3.8.2.3.b of the Technical Specifications. Upon completion of the inspections or cell replacements, the seismic bracing was reinstalled and the battery declared operable within two (2) hours in each case.

08		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50	
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMP. SUBCODE		VALVE SUBCODE		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER																																																					
E C		B		A		Z		Z		7 9		0 2 3		0 3		X		1		A		C		Z		Z		0 0 0		Y		Y		A		C 1 7 3																																																					

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cell inspections and replacements were the result of a reduction in individual  
1 1 cell voltages, although the cells were still operable. This condition was the  
1 2 subject of an informational letter to the Office of Inspection and Enforcement on  
1 3 8/20/79. The complete 201A battery replacement was completed on 10/30/79 and the  
1 4 201B replacement is expected in the next several weeks.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	E	28	1	0	0	29	NA	30
7	8	9	10	11	12	13	14	15	16
ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	6	Z	33	Z	34	NA	35	NA	36
7	8	9	10	11	12	13	14	15	16
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION			
1	7	0	0	0	37	Z	38	NA	39
7	8	9	10	11	12	13	14	15	16
PERSONNEL INJURIES		NUMBER		DESCRIPTION					
1	8	0	0	0	40	NA	41	1292 229	
7	8	9	10	11	12	13	14	15	16
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION					
1	9	Z	42	NA	43	7911070	445		
7	8	9	10	11	12	13	14	15	16
PUBLICITY ISSUED		DESCRIPTION							
2	0	N	44	NA	45				
7	8	9	10	11	12	13	14	15	16

NRC USE ONLY

LER 79-23/03X-1  
Millstone Unit 2  
Docket No. 50-336

#### EVENT DESCRIPTION

During steady state power operation, the seismic bracing for various cells in the 201A and B batteries were removed to allow for cell inspection and/or replacement as outlined below.

<u>DATE</u>	<u>BATTERY</u>	<u>EVOLUTION</u>
10/2/79	201B	Cell inspection
10/3/79	201A	Cell inspection
10/5/79	201B	Replacement of cell 28
10/11/79	201B	Replacement of cell 43
10/17/79	201B	Replacement of cell 41
10/21/79	201B	Replacement of cell 15

These cell inspections and/or replacements resulted in the batteries being declared inoperable in accordance with Section 3.8.2.3.b of the Technical Specifications. Upon the completion of each inspection and/or cell replacement, the seismic bracing was reinstalled and the battery declared operable within two (2) hours in each case.

#### CAUSE DESCRIPTION

The cell inspections and replacements are the result of a reduction in individual cell voltages, although the cells were still operable. This condition was the subject of an informational letter to the Office of Inspection and Enforcement on 8/20/79 which discussed the cause of cell deterioration. The replacement of the 201A battery utilizing temporary seismic bracing was completed on 10/25/79. The replacement of the 201B battery is expected in the next several weeks.

1292 230