

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	3	3	3	7	1	0	2	4	7	9	8	1	1	0	6	7	9	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	8	
---	---	--

[illegible]

0 9
 7 8

A B (11)
 9 10

B (12)
 11

C (13)
 12

S U P P O R T (14)
 13 18

B (15)
 19

Z (16)
 20

(17) LER/RO REPORT NUMBER [7 | 9] [—] [0 | 8 | 5] [/] [0 | 1] [T] [—] [0]
 21 22 23 24 25 26 27 28 29 30 31 32

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			
X	18	F	19	Z	20	Z	21	0	0	0	0	Y	23	N	24	A	25	S	4	2	0
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	4	
---	---	--

7	8	9	8
---	---	---	---

FACILITY STATUS (28) 1 5 E 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 29 30
% POWER 1 0 0 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 29 30
OTHER STATUS NA 30
METHOD OF DISCOVERY D 31 32
DISCOVERY DESCRIPTION ARCHITECT ENGINEER

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 7 8 9 10 11 44

2 33 34 NA

LOCATION OF RELEASE (36)

NA 45 8

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37) Z (38) NA (39)				

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	NA

1707 173

8 9 11 12

LOSS OF OR DAMAGE TO FACILITY (43)

TYPE DESCRIPTION

1 9 7 (42) NA

7 8 9 10

PUBLICITY

ISSUED DESCRIPTION (45)

2 0

N (44) NA

NRC USE ONLY

NRC USE ONLY

NAME OF PREPARER W. Verne Childs

7911090460

PHONE: (315) 342-3840

POWER AUTHORITY OF THE STATE OF NEW YORK
JAMES A. FITZPATRICK NUCLEAR POWER PLANT

DOCKET NO. 50-333

ATTACHMENT TO LER 79-085/01T-0

Page 1 of 1

The Architect-Engineer informed the plant staff that as the result of the Pipe Stress Reanalysis Program, pipe support BFSK-658(H-2) was inoperable. Following the guidelines of the 14 August 1979 letter lifting the Show Cause Order, an analysis has been performed by the Architect-Engineer which demonstrates that the effected system (Fire Protection) remains operable following a Design Basis Earthquake, with this support removed. This support will be upgraded to accept the increased loading resulting from the Shock III analysis as part of our continuing program to correct pipe support deficiencies.

Because the system remains operable, this event is not considered to be a significant hazard to the public health and safety.

A follow up report will be submitted when modification of the support is completed.

1307 174