

LICENSEE EVENT REPORT

CONTROL BLOCK: [] [] [] [] [] [] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 A L B R F 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 37 CAT 38

LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CONT

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	2	5	9	7	1	2	2	6	7	9	8	0	1	2	4	8	0	9
60	61									68	69						74	75						80

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During normal operation drywell continuous air monitor (CAM) 1-RM-90-256 was observed

03 | to have low sample flow. The CAM was declared inoperable and the Chemical Lab. noti-

04 | fied to begin sampling program (T.S.3.6.C.2). There are no redundant systems. There

05 | was no hazard to the public health or safety. There have been no previous failures of

06 | this nature.

07 _____
08 _____

SYSTEM CODE B B (11)		CAUSE CODE E (12)		CAUSE SUBCODE A (13)		COMPONENT CODE I N S T R U (14)				COMP. SUBCODE X (15)		VALVE SUBCODE Z (16)	
EVENT YEAR 7 9 (17)		SEQUENTIAL REPORT NO. 0 3 6 (18)		OCCURRENCE CODE 0 3 (19)		REPORT TYPE L (20)		REVISION NO. 0 (21)		ACTION TAKEN A (22)		FUTURE ACTION Z (23)	
EFFECT ON PLANT Z (24)		SHUTDOWN METHOD Z (25)		HOURS 0 0 0 (26)		ATTACHMENT SUBMITTED Y (27)		NPRD-4 FORM SUB. Y (28)		PRIME COMP. SUPPLIER L (29)		COMPONENT MANUFACTURER S 0 9 3 (30)	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | A pump manufactured by Schwitzer Model 145473 had failed. The pump was replaced and

1 1 | the CAM returned to service. The failure is considered random and no recurrence con-

1 2 | trol action is planned.

1	3	
1	4	

7 8 9
FACILITY STATUS (28) % POWER (29) OTHER STATUS (30) METHOD OF DISCOVERY (31) DISCOVERY DESCRIPTION (32)
1 5 E 0 9 0 NA A Operator observation

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 2 33 34 NA

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
1	7	0	0	0	NA

PERSONNEL INJURIES
NUMBER 000 (40) DESCRIPTION NA (41)

LOSS OF OR DAMAGE TO FACILITY (43) 1828 062
TYPE DESCRIPTION
1 2 3 4 5 6 7 8 9 10 11 12
Z (42) NA

ISSUED PUBLICITY DESCRIPTION (45) NRC USE ONLY

2 1 N 44 NA 68 69 80

NAME OF PREPARER

PHONE:

8001290 398

POOR ORIGINAL

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 7936 Technical Specification Involved 3.6.C.2

Reported Under Technical Specification 6.7.2.b.(2)

Date of Occurrence 12/26/79 Time of Occurrence 0220 Unit 1

Identification and Description of Occurrence:

Sampling pump failed causing low sample flow on 1-RM-90-256.

Conditions Prior to Occurrence:

U-1 at 90%.

U-2 at 90%.

U-3 at 95%.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

The chemical laboratory initiated sampling and analysis program until monitor was returned to service.

Apparent Cause of Occurrence:

Airpump had failed in the radiation monitor.

Analysis of Occurrence:

There was no damage to plant equipment. There was no activity release, no personnel exposure or injury and no danger to the health or safety to the public.

Corrective Action:

Replaced the defective pump and returned the monitor to service.

Failure Data:

None

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 

1828 063