

PILGRIM NUCLEAR POWER STATION
RFD # 1 ROCKY HILL ROAD
PLYMOUTH, MASSACHUSETTS 02360

February 1, 1980

BECO Ltr. #80-15

Director, Region I
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Licensee Event Report 80-003/03L-0

Docket Number 50-293


License DPR-35

Gentlemen:

The attached Licensee Event Report 80-003/03L-0, is hereby submitted. The Operations Review Committee has reviewed this event and classified it as a condition leading to operation in a degraded mode. Leak Rate testing performed in accordance with 10CFR50, Appendix J, has identified that Torus Vacuum Breaker Valve AO 5040A is in need of repair. A followup report enumerating each valve (I.D., Type, Leak Rate, Test Date) for which a maintenance request is initiated as a result of this testing will be issued following the completion of the current refueling outage.

If there are any questions on this subject, please contact us.

Respectfully submitted,


P. J. McGuire
Station Manager
Nuclear Operations

MTM:ep

Enclosures: (3 copies)

LER 80-003/03L-0

cc: Director (40 copies)

Office of Management Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

1866 132

8002040 453

A002
5
ll