

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 F L C R P 3 0 0 - 0 0 0 0 0 - 0 0 4 1 1 1 1 4 - - 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 32

CON'T

01 REPORT SOURCE L 0 5 0 - 0 3 0 2 7 0 2 2 3 7 9 3 0 3 1 2 7 9 9

REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At 0100, while performing daily Operating Surveillance SP-300, it was dis-

03 covered that the heat trace recorder (HTRT-5), for the concentrated boric

04 acid flowpath, was malfunctioning and was rendered inoperable. This created

05 an event contrary to Technical Specification 3.1.2.2.a. Entered 72 hour

06 action statement "A". No hazard to the plant or general public as a flow-

07 path from the borated water storage tank was available and operable.

08 First occurrence of the heat trace system reported.

09

SYSTEM CODE 9 10 CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 13 COMP SUBCODE 14 VALVE SUBCODE 15

PIC 11 E 12 B 13 I N S T R U 14 R 15 Z 16

17 LER NO REPORT NUMBER 18 EVENT YEAR 19 SEQUENTIAL REPORT NO. 20 OCCURRENCE CODE 21 REPORT TYPE 22 REVISION NO.

7 9 21 22 23 24 25 26 27 28 29 30 31 32

ACTION FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM 305 PRIME COMP SUPPLIER COMPONENT MANUFACTURER

A 18 Z 19 Z 20 Z 21 0 0 0 0 22 Y 23 N 24 A 25 L 1 3 0 26

33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of this event is attributed to a failed recorder drive wheel. The

11 drive wheel was replaced and the heat trace recorder was returned to ser-

12 vice. Exited the action statement at 1500. No further corrective action

13 is required.

14

15

FACILITY STATUS 16 POWER 17 OTHER STATUS 18 METHOD OF DISCOVERY 19 DISCOVERY DESCRIPTION 20

E 21 0 9 8 22 NA 23 B 24 Operator observation 25

26

ACTIVITY CONTENT 27 RELEASED OR RELEASE 28 AMOUNT OF ACTIVITY 29 LOCATION OF RELEASE 30

Z 31 Z 32 NA 33 NA 34

35

PERSONNEL EXPOSURES 36 NUMBER 37 TYPE 38 DESCRIPTION 39

0 0 0 40 Z 41 NA 42

43

PERSONNEL INJURIES 44 NUMBER 45 DESCRIPTION 46

0 0 0 47 NA 48

49

LOSS OF OR DAMAGE TO FACILITY 50 TYPE 51 DESCRIPTION 52

Z 53 NA 54

55

PUBLICITY 56 RELEASED DESCRIPTION 57

N 58 NA 59

60

NAME OF PREPARED J. Cooper, Jr. PHONE (904) 795-6486

(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

SUPPLEMENTARY INFORMATION

Report No.: 50-302/79-017/03L-0

Facility: Crystal River Unit #3

Report Date: 12 March 1979

Occurrence Date: 23 February 1979

Identification of Occurrence:

One boron injection flowpath inoperable contrary to Technical Specification 3.1.2.2.a.

Conditions Prior to Occurrence:

Mode 1 power operation (98%)

Description of Occurrence:

At 0100, while performing daily Operating Surveillance SF-300, it was discovered that heat trace recorder 5 was malfunctioning. Heat trace recorder 5 monitors the concentrated boric acid flowpath. Further investigation revealed that the drive wheel had failed. Maintenance restored operability and the recorder was returned to service at 1500.

Designation of Apparent Cause:

The cause of this event is attributed to a failed recorder drive wheel.

Analysis of Occurrence:

No effect on the plant or general public as an alternate flowpath from borated water storage tank was available and operable.

Corrective Action:

The recorder drive wheel assembly was replaced. No further corrective action required.

Failure Data:

First occurrence of the heat trace system reported.

/rc