

CONTROL BLOCK: [] [] [] [] [] [] (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION.)

[0] [1] [O] [H] [D] [B] [S] [1] (2) [] [] - [] [] N P F - [] [3] (3) [4] [1] [1] [1] [1] (4) [] [] (5)

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	-	0	3	4	6	7	1	1	1	0	7	8	8	1	2	0	7	7	8	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 On November 10, 1978 and on November 17, 1978, fluctuating signals from the absolute

0 3 position indicator for Control Rod 4 of Group 3 caused asymmetric rod alarms. Abso-

0 4 lute position indication for this rod was declared inoperable at each of these times,

0 5 placing the unit in the Action Statement of Technical Specification 3.1.3.3. There

0 6 was no danger to the health and safety of the public or to unit personnel. Relative

0 7 position indication, as well as zone reference indication for Rod 4, Group 3 was

0 8 operable. (NP-33-78-135)

SYSTEM CODE I F 11		CAUSE CODE E 12		CAUSE SUBCODE A 13		COMPONENT CODE E L E C C N 14		COMP. SUBCODE Z 15		VALVE SUBCODE Z 16	
EVENT YEAR 7 8 21 22		SEQUENTIAL REPORT NO. 1 1 3 24 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		REVISION NO. 1 32		COMPONENT MANUFACTURER B 3 6 5 26 44 47	
ACTION TAKEN X 18		FUTURE ACTION C 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22 37 40		ATTACHMENT SUBMITTED Y 23	
LER/RO REPORT NUMBER 17		PRIME COMP. SUPPLIER A 25		NPRD-4 FORM SUB. Y 24		PRIME COMP. SUPPLIER A 25		PRIME COMP. SUPPLIER A 25		PRIME COMP. SUPPLIER A 25	

33 34 35 36

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 After access to containment was permitted, investigation of the absolute position in-

1 1 dication for Control Rod 4 of Group 3 resumed by testing the individual components of

1 2 the PI string. The cause of the occurrence has been determined to be an intermittent

1 3 failure of a component within the position indicator tube. The position indicator

1 4 tube was replaced.

80

7 8 9 FACILITY STATUS (28) E 1 5 29 0 4 9 NA 44 30 OTHER STATUS 45 METHOD OF DISCOVERY A 31 46 Fluctuating Signals 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 DISCOVERY DESCRIPTION (32)

7 8 9 10 12 13

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 2 33 34 NA

44

45 NA LOCATION OF RELEASE (36) 80

7		8		9		10		11	
PERSONNEL EXPOSURES									
NUMBER				TYPE		DESCRIPTION			
1	7	0	0	0	(37)	Z	(38)	NA (39)	

PERSONNEL INJURIES		DESCRIPTION	
1	2	3	4
1	8	40	NA

7		8	9	10		11	
1		2		3		4	
TYPE		DESCRIPTION		43			
1	9	Z	42	NA			

NRC USE ONLY

PUBLICITY
 ISSUED DESCRIPTION (45)
 2 0 N (44) NA 7903230170
 2 9 9 10 68 69 80
 419-259-5000, Ext. 230

DVR 78-171 & NAME OF PREPARER

Susan A. Kovach

PHONE: 419-259-5000, Ext. 230