

LICENSEE EVENT REPORT

"Update Report - Previous Report Date 05-23-79"

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M A P P S I 2 0 0 0 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 38

CON'T

0 1
8

REPORT SOURCE L 6 0 5 0 - 0 2 9 3 7 0 5 1 9 7 9 8 0 6 0 6 7 9 9
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On May 19, 1979, while shutdown for modifications to seismic restraints, recirculation
0 3 | pump P-201A was started with delta temperature between loops greater than 50 degrees.
0 4 | When the pump was started it was also observed that reactor coolant temperature was
0 5 | greater than 212 degrees and primary containment integrity was not being maintained.
0 6 | The recirculation pump was secured immediately, primary containment integrity was
0 7 | established and reactor cooled to less than 212 degrees.

80

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE	
C	B	A	A	A	P	U	M	P	X	X	B	Z	
9	10	11	12	13	14	15	16	17	18	19	20		
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.			
7	9	—	0	1	8	/	0	1	T	—	1		
21	22	23	24	25	26	27	28	29	30	31	32		
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED			
X	H	Z	Z	0	0	0	0	N	N	N	B		
33	34	35	36	37	38	39	40	41	42	43	44		
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS													

0 The cause for exceeding the delta temperature limitations was failure to follow station
1 operating procedures and the violation of primary containment resulted from trending
2 temperature monitors which were not responding to the changes in reactor coolant
3 temperature increase. Disciplinary action was taken against the personnel involved,
4 and they were rescheduled for specific training on Recirc. Operation.

2285 042

7906120305

NRC USE ONLY

NAME OF PREPARER Charles J. Mathis

PHONE: 617-746-7900