

## LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 F L C R P 3 00-000000-00 41111 4-5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 38 39

CON'T

01 REPORT SOURCE L 050-0302 011979 8021379

REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At 1346 while performing Engineered Safeguards Monthly Functional Test,

03 (SP-130), it was discovered that RC3-GP3-BL4 light did not extinguish when

04 the test switch was returned to the off position. Investigation revealed

05 that relay AR in cabinet 5C had failed. This created an event contrary to

06 Technical Specification 3.3.2.1. Entered Action Statement 9. Operability

07 was restored in two hours. No affect on public health and safety as redun-

08 dant channels were operable. Eleven previous occurrences reported. Fourth

09 occurrence of this type.

SYSTEM CODE 9 10 CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 13 COMP SUBCODE 14 VALVE SUBCODE 15

09 S H 11 E 12 X 13 R E L A Y X 14 A 15 Z 16

LER NO REPORT NUMBER 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

7 9 0 0 8 0 3 L 0

ACTION TAKEN 33 34 FUTURE ACTION 35 EFFECT ON PLANT 36 SHUTDOWN METHOD 37 HOURS 38 ATTACHMENT SUBMITTED 39 NPD-4 FORM SUB 40 PRIME COMP SUPPLIER 41 COMPONENT MANUFACTURER 42

1 X Z 19 Z 20 Z 21 00000 Y 23 N 24 A 25 C 360 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of this event was attributed to dirty contacts in the AR relay.

11 The relay was sprayed with a cleaner, functionally tested, and returned to

12 operable status. Engineering study (PD-718) associated with air filtration

13 of engineering safeguards cabinets is being conducted to prevent recurrence.

14

FACILITY STATUS 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 E 28 0 6 8 29 NA 30 B 31 Technician observation 32

ACTIVITY CONTENT 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 Z 33 Z 34 NA 35 NA 36 NA 37 NA 38 NA 39 NA 40 NA 41 NA 42 NA 43 NA 44 NA 45 NA 46 NA 47 NA 48 NA 49 NA 50 NA

PERSONNEL EXPOSURES 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70

1 0 0 0 37 Z 38 NA 39 NA 40 NA 41 NA 42 NA 43 NA 44 NA 45 NA 46 NA 47 NA 48 NA 49 NA 50 NA

PERSONNEL INJURIES 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70

1 0 0 0 40 NA 41 NA 42 NA 43 NA 44 NA 45 NA 46 NA 47 NA 48 NA 49 NA 50 NA

LOSS OF OR DAMAGE TO FACILITY 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70

1 Z 42 NA 43 NA 44 NA 45 NA 46 NA 47 NA 48 NA 49 NA 50 NA

PUBLICITY 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70

1 N 54 NA 55 NA 56 NA 57 NA 58 NA 59 NA 60 NA 61 NA 62 NA 63 NA 64 NA 65 NA 66 NA 67 NA 68 NA 69 NA 70 NA

ISSUED DESCRIPTION 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70

2 N 54 NA 55 NA 56 NA 57 NA 58 NA 59 NA 60 NA 61 NA 62 NA 63 NA 64 NA 65 NA 66 NA 67 NA 68 NA 69 NA 70 NA

NAME OF PREPARER J. Cooper PHONE (904) 795-6486

7902220120

(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

SUPPLEMENTARY INFORMATION

Report No.: 50-302/79-008/03L-0

Facility: Crystal River Unit #3

Report Date: 13 February 1979

Occurrence Date: 19 January 1979

Identification of Occurrence:

One inoperable engineered safety feature actuation system instrument channel contrary to Technical Specification 3.3.2.1.

Conditions Prior to Occurrence:

Mode 1 power operation (68%)

Description of Occurrence:

At 1346 while performing the Engineered Safeguards Monthly Functional Test (SP-130), it was discovered that RC3-GP3-BL4 light would not extinguish when the test switch was returned to the off position. Upon investigation it was determined that relay AR had failed. Operability was restored in two hours.

Designation of Apparent Cause:

The cause of this event was found to be dirty contacts in the AR relay.

Analysis of Occurrence:

There was no hazard to the plant or general public as the affected channel was in a test mode with the two remaining channels operable.

Corrective Action:

The relay was sprayed with a contact cleaner, tested, and returned to operable status. Engineering study (PD-718) associated with air filtration of engineered safeguards cabinets is being conducted to prevent recurrence.

Failure Data:

Eleven previous occurrences reported. Fourth occurrence of this type.

/rc