

0	1	N	C	B	E	P	2	2	0	0	-	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4			5
7	8	9					14	15											25	26					30		57	CAT	58
LICENSEE CODE		LICENSE NUMBER										LICENSE TYPE																	

REPORT
SOURCE

L	6	0	5	0	-	0	3	2	7	0	1	1	5	7	9	8	0	2	1	3	7	9	9	
60	61	DOCKET NUMBER						68	69	EVENT DATE						74	75	REPORT DATE						80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 Diesel Generator No. 3 was removed from service for plant modifications. Before the

03 Diesel Generator could be declared operable and returned to service, the Diesel

0	4	Generator was tested. The Generator failed to produce any output voltage.
---	---	---

05 | (Technical Specification 3.8.1.1)

0	6	
---	---	--

0	8	
---	---	--

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
 [0] [9] [E] [E] (11) [E] (12) [X] (13) [C] [K] [T] [B] [R] [K] (14) [E] (15) [Z] (16)
 7 8 9 10 11 12 13 14 15 16 17 18 19 20

(17) LER RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

7	9	—	0	0	2	—	0	3	L	—	0
21	22	23	24	25	26	27	28	29	30	31	32

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER					
X	18	B	19	Z	20	Z	21	0	0	0	0	22	Y	23	Y	24	A	25	G	0	8	0	26
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	Failure of the Generator field reset switch to make good contact caused this event.
---	---	---

1	1	This switch required cycling before contact closure was adequately made. The switch
---	---	---

1	2
---	---

 operated normally after cycling. The switches for Diesel Generator No. 3 and No. 4

1 3 | were scheduled for examination during the upcoming Diesel Generator shutdowns. The |

14 | No. 3 Generator was returned to service within 45 minutes. (cont.)

7		8		9		FACILITY STATUS		% POWER		OTHER STATUS		(30)		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		(32)		80					
1		5		E		(28)		0		9		1		(29)		NA		B		(31)		Operability Check		80	
7		8		9				10		11		12		13		44		45		46				80	

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 2 33 2 34 NA

7 8 9 10 11 44

LOCATION OF RELEASE (36)

NA

45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	2	(38)	NA	(39)

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	8	0	0
0	0	0	40
		NA	

8 9		11 12		80	
LOSS OF OR DAMAGE TO FACILITY				(43)	
TYPE		DESCRIPTION			
1	9	Z	(42)	NA	

8 9 10 80

PUBLICITY

ISSUED DESCRIPTION (45) 790222 0147 NRC USE ONLY

2 0 N (44) NA

NAME OF PREPARER A. C. Tollison, Jr. 2/13/78

PHONE: (919) 457-6701

LER CONTINUATION -- RO #-79-2

Facility: BSEP Unit #2

Event Date 1/15/79

Field reset switches for Diesel Generator No. 1 and No. 2 were subsequently examined and found to be satisfactory. These switches also operated normally.

It is believed the contacts for the No. 3 Generator field reset switch were dirty. This is considered an isolated event and no further corrective action is required.