

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 M D C C N 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5

N/T

1 L 6 0 5 0 0 0 3 1 8 7 0 5 1 9 7 9 8 0 5 2 5 7 9 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2 During the performance of surveillance testing the containment air lock outer
 3 door air leakage was found to be in excess of that allowed by Tech. Spec.
 4 3.6.1.3.b at 2145. Corrective action was completed and a satisfactory leak
 5 rate test was performed at 1530 on 5/20/79. The inner door remained closed
 6 and sealed while the outer door was inoperable. Throughout this period the
 7 total containment air leakage never exceeded the limit of T.S. 3.6.1.2.b.
 8 LER's 77-13 (U-1) and 77-19 (U-2) describe similar events.

9 S A 11 E 12 B 13 P E N E T R 14 A 15 Z 16

17 LER NO. 7 9 - 0 1 5 0 3 L 0

ACTION TAKEN A 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 A 25 C 3 1 1 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

0 The cause of the excessive leakage was a failed door gasket. This is
 1 considered a normal end of life failure. New door gaskets were installed
 2 and door latch rollers adjusted. Seals were retested satisfactory.

5 E 28 1 0 0 29 NA B 31 Surveillance Test 32

6 Z 33 Z 34 NA NA 36

7 0 0 0 37 Z 38 NA 39

8 0 0 0 40 NA 41

9 Z 42 NA 43

0 Z 44 NA 45

2266 245

7906050 265 S

NAME OF PREPARER J. S. Lagiewski/M. J. Miernicki

PHONE: (301) 234-7942/7962