

CONTROL BLOCK:

--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1		N	C	B	E	P	1	(2)	0	0	-	0	0	0	0	0	-	0	0	(3)	4	1	1	1	1	(4)			(5)	
8	9		LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT 58	

CON'T

REPORT SOURCE L 6 0 5 0 - 0 3 2 5 7 0 6 1 3 7 9 8 0 6 2 7 7 9 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During normal operation, 1 B standby Gas Train was de-energized for approximately

03 | 40 minutes due to an electrical problem in the 480 volt sub-station 1XF.

Q 4

05 | (Technical Specifications 3.6.6.1, 6.9.1.9b)

0	6	
---	---	--

07

0	8	
---	---	--

0 9 8

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

S C 11 E 12 A 13 C K T B K R 14 A 15 Z 16

9 10 11 12 13 14 15 16 17 18 19 20

(17) LER/RO REPORT NUMBER 7 9 —

EVENT YEAR 0 3 9 /

SEQUENTIAL REPORT NO. 0 3 —

OCCURRENCE CODE 0 3 —

REPORT TYPE L —

REVISION NO. 0 —

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER				
X	18	Z	19	Z	20	Z	21	0	0	0	0	22	Y	23	N	24	N	25	G	0	8	0
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The breaker for the 1 B Reactor Water Cleanup (RWCU) pump appeared to have developed

111 | a hot spot, possibly due to a loose connection, which drew excessive current, burned th

[1] [2] insulation, and caused the feeder from E-6 to 1XF to trip. The RWCU breaker was re-

13 | moved and 1XF was re-energized from E-6. A preventive maintenance instruction (Con't)

1	4	
---	---	--

FACILITY STATUS (1) 5 (E) (28) % POWER (0) 9 7 (29) OTHER STATUS (30) NA METHOD OF DISCOVERY (A) (31) DISCOVERY DESCRIPTION (32) Operator Observation

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 Z (33) Z (34) NA

7 8 9 10 11 44

NA LOCATION OF RELEASE (36)

45 46

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	(39)
8	9	11	12	13					80

PERSONNEL INJURIES										
NUMBER			DESCRIPTION							
1	8	0	0	0	40	NA				

		LOSS OF OR DAMAGE TO FACILITY		(43)
		TYPE	DESCRIPTION	
1	9	Z	(42) NA	2147 091
8	9	10		

PUSLICY ISSUED DESCRIPTION (45) 7906290 371 NRC USE ONLY
 2 0 N 44 NA

2147 09:

7906290 37/

NRC USE ONLY

457-9521

A. C. Tollison, Jr.

00 01 7.926

LER CONTINUATION -- RO# 1-79-039

Facility: BSEP Unit #1

Event Date: 6-13-79

is currently in effect to check terminal tightness on these breakers. This event will be reviewed by all electricians and I&C technicians to ensure that leads removed or loosened for maintenance are tightened properly when the work is completed.

2147 092