

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1

PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION

0 1 F L Q R P 3 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 - - 5  
 7 8 9 14 15 25 26 30 37 CAT 58  
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T  
 0 1 REPORT SOURCE L 5 0 5 0 - 0 3 0 2 7 0 1 0 6 7 9 3 0 1 2 6 7 9 9  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
 DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  
 0 2 At 0242, during Rx runback following a turbine trip, it was discovered  
 0 3 that a main feedwater block valve (FWV -30) did not close. This is contrary  
 0 4 to Technical Specification 3.3.2.1, Table 3.3-5. No effect upon public  
 0 5 health and safety as redundant systems were available and operable. Two  
 0 6 previous occurrences of this type reported, but first occurrence for FWV-30.  
 0 7  
 0 8

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE  
 0 9 H H 11 X 12 Z 13 V A L V E X 14 E 15 D 16  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20  
 LER NO EVENT YEAR SEQUENTIAL REPORT NO OCCURRENCE CODE REPORT TYPE REVISION NO  
 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
 1 7 9 0 0 3 0 3 L 0

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NRC-4 FORM 305 PRIME COMP SUPPLIER COMPONENT MANUFACTURER  
 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47  
 X 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 A 25 C 2 5 5 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27  
 1 0 The cause of this anomaly is attributed to FWP-30 being stuck on its back  
 1 1 seat. FWV-30 was manually taken off its backseat and cycled. Operability  
 1 2 was restored following satisfactory completion of engineering safeguards  
 1 3 actuation response time test (SP-135).  
 1 4

FACILITY STATUS & POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32  
 1 5 X 28 0 4 5 29 Runback A 31 Operator observation  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36  
 1 6 Z 33 Z 34 NA NA  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  
 1 7 0 0 0 37 Z 38 NA  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

PERSONNEL INJURIES NUMBER DESCRIPTION 41  
 1 8 0 0 0 40 NA  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43  
 1 9 Z 42 NA  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

PUBLICITY ISSUED DESCRIPTION 45 NRC USE ONLY  
 2 0 N 44 NA  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

NAME OF PREPARER J. Cooper PHONE (904) 795-6486

(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

7902050 187

SUPPLEMENTARY INFORMATION

Report No.: 50-302/79-003/03L-0

Facility: Crystal River Unit #3

Report Date: 26 January 1979

Occurrence Date: 6 January 1979

Identification of Occurrence:

Feedwater block valve (FWV-30) inoperable contrary to response time specified in Technical Specification 3.3.2.1, Table 3.3-5.

Conditions Prior to Occurrence:

At 0242, during a reactor runback following a turbine trip, it was discovered that a main feedwater block valve (FWV-30) did not close. "A" feedwater line was isolated and the reactor manually tripped. Feedwater flow was re-established with emergency feedwater pump (EFP-2). FWV-30 was rendered operable at 0615, 6 January 1979.

Designation of Apparent Cause:

The cause of this anomaly was attributed to FWV-30 being stuck on its back seat.

Analysis of Occurrence:

There was no hazard to the plant or general public as redundant emergency feedwater systems were available and operable.

Corrective Action:

No corrective action necessary. FWV-30 was manually taken off its back seat, cycled and rendered operable after satisfactory completion of engineering safeguards actuation response time test (SP-135).

Failure Data:

Two previous occurrences of this type but first occurrence of FWV-30.

/rc