

## LICENSEE EVENT REPORT

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	V	A	N	A	S	1	2	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			6
7	8	9	LICENSEE CODE					14	15	LICENSE NUMBER					24	25	LICENSE TYPE					30	31	CAT ID				

CONT

0	1	L	6	0	5	0		0	3	3	8	7	0	1	0	8	7	9	0	0	2	0	1	7	9	5		
7	8	REPORT SOURCE					60	61	DO T NUMBER					66	67	EVENT DATE					74	75	REPORT DATE					80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While performing 1-PT-36.1 (A), it was found that the SSPS steam generator 3 Hi Hi

03 level test on the SSPS test panel was faulty which prevented testing of this channel.

04 This is contrary to T.S. 3.3.2.1. Action Statement #13 was entered and the channel

05 restored to operability within the 2 hour time allowance. This event is reportable

06 as per T.S. 6.9.1.9.b.

07

08

09

0	1	I	B	11	E	12	G	13	I	N	S	T	R	U	14	Y	15	Z	16				
7	8	SYSTEM CODE			9	10	CAUSE CODE		11	CAUSE SUBCODE		12	COMPONENT CODE			13	COMP. SUBCODE		14	VALVE SUBCODE		15	16

17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32						
1-PT-36.1		EVENT YEAR		79		SEQUENTIAL REPORT NO.		004		OCCURRENCE CODE		03		REPORT TYPE		1		REVISION NO.		0	

33	34	35	36	37	38	39	40	41	42	43	44	45	46	47			
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
A		Z		Z		Z		0000		Y		Y		N		W120	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of the event was a faulty Universal Logic Card on the test panel. The

11 Logic Card was replaced and the periodic test was performed satisfactory. No further

12 corrective action was required.

13

14

1	2	E	28	0	9	7	29	N/A	30	B	31	Periodic Test	32													
7	8	FACILITY STATUS			9	10	% POWER			11	12	OTHER STATUS			13	14	METHOD OF DISCOVERY			15	16	DISCOVERY DESCRIPTION			17	18

1	2	Z	33	Z	34	N/A	35	N/A	36							
7	8	ACTIVITY RELEASED			9	10	AMOUNT OF ACTIVITY			11	12	LOCATION OF RELEASE			13	14

1	2	0	0	0	37	Z	38	N/A	39			
7	8	PERSONNEL EXPOSURES			9	10	DESCRIPTION			11	12	13

1	2	0	0	0	40	N/A	41				
7	8	PERSONNEL INJURIES			9	10	DESCRIPTION			11	12

1	2	Z	42	N/A	43						
7	8	LOSS OF OR DAMAGE TO FACILITY			9	10	DESCRIPTION			11	12

1	2	N	44	N/A	45						
7	8	PUBLICITY			9	10	DESCRIPTION			11	12

NAME OF PREPARER W. R. Cartwright

PHONE 703-894-5151

7902060309

NRC USE ONLY

Description of Event:

On 01-08-79, during the performance of periodic test 1-PT-36.1(A), it was discovered that SSPS Steam Generator 3 Hi Hi Level test on the SSPS test panel was faulty which prevented testing of this channel. This is contrary to T.S. 3.3.2.1.

Action Statement #13 was entered and the channel restored to operability within the 2 hour time allowance.

This event is reportable as per T.S. 6.9.1.9.b.

Probable Consequences of Occurrence:

The SSPS Steam Generator Hi Hi Level Test is part of the Engineered Safety Feature Instrumentation System. The operability of this system is required to test the operability of the various ESF functions. After this faulty card was replaced, the test showed that the ESF channel was operable and capable of providing the necessary protection. There was no effect upon the safe operation of the plant and as a result, the public health and safety was not endangered.

Cause of Occurrence:

The cause of the event was a faulty Universal Logic card in the SSPS test cabinet.

Immediate Corrective Action:

The faulty logic card was replaced and the periodic test was performed.

Scheduled Corrective Action:

No further corrective action was required.

Actions Taken to Prevent Recurrences:

No further corrective action was required.