

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 0 H D B S 1 2 0 0 - 0 0 N P F - 0 3 3 4 1 1 1 1 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0 1 L 6 0 5 0 - 0 3 4 6 7 0 1 0 4 7 9 8 0 1 3 1 7 9 9

REPORT SOURCE 60 61 DOCKET NUMBER 65 66 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 0800 hours on 1/4/79, Control Room Emergency Ventilation System (EVS) Damper HV5311F

0 3 | was declared inoperable. Surveillance testing had determined a deficiency existed.

0 4 | The damper was then blocked open to maintain Control Room ventilation. This occur-

0 5 | rence is being reported as documentation of a component failure. There was no danger

0 6 | to the health and safety of the public or unit personnel. The failure of this damper

0 7 | did not render either train of the Control Room EVS inoperable. The subject damper

0 8 | is redundant in the Control Room EVS train. (NP-33-79-04)

0 9 S G 11 E 12 X 13 V A L V O P 14 J 15 D 16

SYSTEM CODE 5 10 CAUSE CODE 11 12 CAUSE SUBCODE 12 13 COMPONENT CODE 13 18 COMP. SUBCODE 19 19 VALVE SUBCODE 20 20

17 7 9 0 0 3 0 3 L 0

LER/RO REPORT NUMBER 21 22 SEQUENTIAL REPORT NO. 24 26 OCCURRENCE CODE 28 29 REPORT TYPE 30 31 REVISION NO. 32 32

C 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 Y 24 A 25 C 6 2 6 26

ACTION TAKEN 33 34 FUTURE ACTION 34 35 EFFECT ON PLANT 35 36 SHUTDOWN METHOD 36 37 HOURS 37 40 ATTACHMENT SUBMITTED 41 42 NPD-4 FORM SUB. 42 43 PRIME COMP. SUPPLIER 43 44 COMPONENT MANUFACTURER 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The pneumatic operator was found to be leaking and a new operator was installed. The

1 1 | damper was operated and tested for response time. The damper was declared operable

1 2 | at approximately 1200 hours on 1/12/79. All other Control Room EVS operators

1 3 | similar to the one that failed have been inspected.

1 4 E 28 0 9 9 29 NA 30 B 31 Surveillance Test ST 5032.01 32

FACILITY STATUS 7 8 % POWER 9 10 OTHER STATUS 13 14 METHOD OF DISCOVERY 45 46 DISCOVERY DESCRIPTION 46 80

1 5 Z 33 Z 34 NA 35 NA 36

ACTIVITY CONTENT 7 8 RELEASED OF RELEASE 9 10 AMOUNT OF ACTIVITY 13 14 LOCATION OF RELEASE 13 80

1 6 0 0 0 37 Z 38 NA 39

PERSONNEL EXPOSURES 7 8 NUMBER 9 10 TYPE 11 12 DESCRIPTION 13 14

1 7 0 0 0 40 NA 41

PERSONNEL INJURIES 7 8 NUMBER 9 10 DESCRIPTION 13 14

1 8 Z 42 NA 43

LOSS OF OR DAMAGE TO FACILITY 7 8 TYPE 9 10 DESCRIPTION 13 14

1 9 N 44 NA 45

PUBLICITY 7 8 ISSUED 9 10 DESCRIPTION 13 14

2 0 N 44 NA 45

7902060332

NRC USE ONLY

James Rudolph

419-259-5000, Ext. 234

TOLEDO EDISON COMPANY
DAVIS-BESSE NUCLEAR POWER STATION UNIT ONE
SUPPLEMENTAL INFORMATION FOR LER NP-33-79-04

DATE OF EVENT: January 4, 1979

FACILITY: Davis-Besse Unit 1

IDENTIFICATION OF OCCURRENCE: Control Room Emergency Ventilation System (EVS) Damper HV5311E rendered inoperable

Conditions Prior to Occurrence: The unit was in Mode 1, with Power (MWT) = 2750, and Load (Gross MWE) = 920.

Description of Occurrence: At 0800 hours on January 4, 1979, Control Room EVS Damper HV5311E was declared inoperable. The mechanical control linkage for HV5311E, the suction damper for normal Control Room Ventilation Fans, was disconnected, and the damper blocked open to maintain Control Room ventilation pending cylinder repair or replacement of the complete mechanism. The failure was detected by a power plant repairman who was investigating the cause of suspended Surveillance Test ST 5032.01, "Monthly Functional Test of the Radiation Monitoring System".

This occurrence is being reported as documentation of a component failure.

Designation of Apparent Cause of Occurrence: The pneumatic operator for HV5311E was found to be leaking, therefore rendering insufficient service to the subject damper.

Analysis of Occurrence: There was no danger to the health and safety of the public or to unit personnel. The failure of this damper did not render either train of the Control Room EVS inoperable. The subject damper is redundant in the Control Room EVS train.

Corrective Action: A new operator was installed per Maintenance Work Order 79-1193. The damper was operated and tested for response time per ST 5076.03, "Control Room EVS Refueling Test". The damper was declared operable at approximately 1200 hours on January 12, 1979. All other Control Room EVS operators similar to the one that failed have been inspected for cylinder leakage and none were reported to be leaking.

Failure Data: There have been no previous similar reportable occurrences of an EVS damper removed from service due to pneumatic operator trouble.