

LICENSEE EVENT REPORT

* CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N C B E P 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 57 CAT 58

CON'T

0 1 REPORT SOURCE L 6 0 5 0 - 0 3 2 4 7 0 1 0 9 7 9 8 0 2 0 7 7 9 9
7 8 63 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 RHR pump discharge pressure switch Ell-PS-N020D failed, causing a pump running annun-

0 3 ciator. Investigation revealed sticking contacts on the pressure switch.

0 4 (Technical Specification 3.3.3)

0 5

0 6

0 7

0 8

0 9 SYSTEM CAUSE CAUSE COMPONENT COMP. VALVE
CODE CODE SUBCODE CODE SUBCODE SUBCODE
S F 11 E 12 D 13 I N S T R U 14 S 15 Z 16
9 10 11 12 13 18 19 20
17 LER RO EVENT YEAR SEQUENTIAL OCCURRENCE REPORT REVISION
REPORT NUMBER 7 9 0 0 5 0 3 L 0
21 22 23 24 26 27 28 29 30 31 32
ACTION FUTURE EFFECT SHUTDOWN HOURS ATTACHMENT NPRD-4 PRIME COMP. COMPONENT
TAKEN ACTION ON PLANT METHOD 22 SUBMITTED FORM SUB. SUPPLIER MANUFACTURER
E 18 G 19 Z 20 Z 21 0 0 0 0 N 23 N 24 A 25 B 0 6 9 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Pressure switch Ell-PS-N020D failure was caused by contact plunger stem corrosion.

1 1 The switch was disassembled, cleaned and returned to service after recalibration with-

1 2 in 11 hours. Frequency of P.T. 3.1.1P (which verifies the operability of this switch)

1 3 will be changed from once per month to twice per month. The increased surveillance

1 4 frequency will help to keep the plunger free from sticking. Also, increased (Cont'd.)

1 5 FACILITY % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
STATUS 0 9 2 NA A Control Room Annunciator
7 8 9 10 11 12 13 44 45 46 80

1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
Z 33 Z 34 NA NA
7 8 9 10 11 12 13 44 45 80

1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
0 0 0 37 Z 38 NA
7 8 9 10 11 12 13 80

1 8 PERSONNEL INJURIES NUMBER DESCRIPTION
0 0 0 40 NA
7 8 9 10 11 12 80

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
Z 42 NA
7 8 9 10 80

2 0 PUBLICITY ISSUED DESCRIPTION
N 44 NA
7 8 9 10 80

790214 0179

NRC USE ONLY

NAME OF PREPARER A. C. Tollison, Jr.

PHONE 919-457-6701

LER SUPPLEMENT -- RO# 2-79-5

Facility: BSEP Unit #2

Event Date 1/9/79

frequency will provide earlier identification of instrument trends. These actions should prevent similar events from occurring. Similar switches on both units were inspected and found in good condition.