

# LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	G A E I H 1	2	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	3	4 1 1 1 1 1	4	5
8	9	14	15	20	26	30	57 CAT 58
LICENSEE CODE      LICENSE NUMBER      LICENSE TYPE							

  

01	L	6	0 5 0 0 0 0 3 2 1	7	0 1 1 2 4 7 9	8	0 2 0 8 7 9	9
8	60	61	68	69	74	75	80	
REPORT SOURCE      DOCKET NUMBER      EVENT DATE      REPORT DATE								

**EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)**

02 | On January 24, 1979, with the reactor at 55 cps on the SRM's the Tech. Spec. require-

03 | ment that Secondary Containment Violation Surveillance be performed immediately after

04 | restoration of Secondary Containment was not met. There are no consequences as the

05 | procedure was acceptably performed approximately four hours later.

06 |

07 |

08 |

09	S	C	11	A	12	Z	13	Z	Z	Z	Z	Z	Z	14	Z	15	Z	16
8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26
SYSTEM CODE      CAUSE CODE      CAUSE SUBCODE      COMPONENT CODE      COMP. SUBCODE      VALVE SUBCODE																		

  

17	7	9	21	22	23	0	1	4	24	25	0	3	28	29	30	31	32
8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
LER/RO REPORT NUMBER      EVENT YEAR      SEQUENTIAL REPORT NO.      OCCURRENCE CODE      REPORT TYPE      REVISION NO.																	

  

X	18	Z	19	Z	20	Z	21	0	0	0	0	22	N	23	N	24	Z	25	Z	9	9	9	9	26	
8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33
ACTION TAKEN      FUTURE ACTION      EFFECT ON PLANT      SHUTDOWN METHOD      HOURS      ATTACHMENT SUBMITTED      NRC-4 FORM SUB.      PRIME COMP. SUPPLIER      COMPONENT MANUFACTURER																									

**CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)**

10 | Cause of event was mis-interpretation of Tech. Spec. requirement to prove ability of

11 | standby gas treatment system to maintain 1/2 inch of water vacuum pressure under calm

12 | (<5 mph) wind conditions. Since wind speed was greater than 15 mph, licensed person-

13 | nel thought test could not be performed. Corrective action was to issue a memo inter-

14 | preting the requirement indicating that the test be run regardless of wind conditions

15	D	28	0	0	0	29	N/A	30	A	31	Observation by personnel	32
8	9	10	11	12	13	14	15	16	17	18	19	20
FACILITY STATUS      % POWER      OTHER STATUS      METHOD OF DISCOVERY      DISCOVERY DESCRIPTION												

  

16	Z	33	Z	34	N/A	35	N/A	36
8	9	10	11	12	13	14	15	16
ACTIVITY CONTENT      RELEASED OF RELEASE      AMOUNT OF ACTIVITY      LOCATION OF RELEASE								

  

17	0	0	0	37	Z	38	N/A	39
8	9	10	11	12	13	14	15	16
PERSONNEL EXPOSURES      NUMBER      TYPE      DESCRIPTION								

  

18	0	0	0	40	N/A	41	N/A	42
8	9	10	11	12	13	14	15	16
PERSONNEL INJURIES      NUMBER      DESCRIPTION								

  

19	Z	43	N/A	44	N/A	45	N/A	46
8	9	10	11	12	13	14	15	16
LOSS OF OR DAMAGE TO FACILITY      TYPE      DESCRIPTION								

  

20	N	47	N/A	48	N/A	49	N/A	50
8	9	10	11	12	13	14	15	16
PUBLICITY      ISSUED      DESCRIPTION								

790215 0394

NRC USE ONLY

NAME OF PREPARER Tom Greene, Supt. of Plt. Eng. Services PHONE (912) 367-7781