

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N J O C P I 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
8 9 14 15 25 26 30 57 CAT 58
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T

0 1 REPORT SOURCE L 6 0 5 0 0 0 2 1 9 7 0 2 0 6 7 9 8 0 2 2 7 7 9 9
60 61 68 69 74 75 80
 DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operation, while performing the isolation condenser auto-

0 3 matic actuation test and calibration, the RE-15B trip point was found to

0 4 be less conservative than specified in the Tech Specs. The only safety

0 5 significance of this event was the loss of redundancy in the pressure

0 6 switch actuation of the prescribed setpoint.

0 7

0 8

7 8 9

0 9 SYSTEM CODE S F 11 CAUSE CODE E 12 CAUSE SUBCODE X 13 COMPONENT CODE C K T B R K 14 COMP. SUBCODE E 15 VALVE SUBCODE Z 16

17 LER/RO REPORT NUMBER 7 9 21 22 23 24 26 27 28 29 30 31 32 REVISION NO. 0

33 ACTION TAKEN E 18 34 FUTURE ACTION Z 19 35 EFFECT ON PLANT Z 20 36 SHUTDOWN METHOD Z 21 37 HOURS 0 0 0 0 40 41 ATTACHMENT SUBMITTED Y 23 42 NPRD-4 FORM SUB. Y 24 43 PRIME COMP. SUPPLIER N 25 44 COMPONENT MANUFACTURER B 0 6 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Immediate corrective action was to reset RE-15B to trip at 1068 psig.

1 1 No further action is contemplated.

1 2

1 3

1 4

7 8 9

1 5 FACILITY STATUS E 28 10 % POWER 0 9 9 29 13 OTHER STATUS NA 30 44 METHOD OF DISCOVERY B 31 45 DISCOVERY DESCRIPTION 32 ISO Condenser Auto Actuation Test

1 6 ACTIVITY CONTENT Z 33 10 RELEASED OF RELEASE Z 34 11 AMOUNT OF ACTIVITY NA 35 44 LOCATION OF RELEASE 36 NA

1 7 PERSONNEL EXPOSURES 0 0 0 37 11 TYPE Z 38 12 DESCRIPTION 39 NA

1 8 PERSONNEL INJURIES 0 0 0 40 11 DESCRIPTION 41 NA

1 9 LOSS OF OR DAMAGE TO FACILITY Z 42 11 TYPE NA 43 12 DESCRIPTION

2 0 PUBLICITY Y 44 10 ISSUED DESCRIPTION 45 Weekly news release - March 12, 1979.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 00

7903070333

NRC USE ONLY



Jersey Central Power & Light Company
Madison Avenue at Punch Bowl Road
Morristown, New Jersey 07960
(201) 455-8200

OYSTER CREEK NUCLEAR GENERATING STATION
Forked River, New Jersey 08731

Licensee Event Report
Reportable Occurrence No. 50-219/79-2/3L-0

Report Date

February 27, 1979

Occurrence Date

February 6, 1979

Identification of Occurrence

Violation of the Technical Specifications, paragraph 2.3.5, reactor high pressure isolation condenser initiation pressure switch RE-15B tripped at a value greater than that specified in the Technical Specifications. This event is considered to be a reportable occurrence as defined in the Technical Specifications, paragraph 6.9.2.b.1.

Conditions Prior to Occurrence

Plant parameters at the time of the occurrence were:

Power: Reactor, 1918.16 MWt
Generator, 647 MWe
Flow: Feedwater, 7.177×10^6 lb/hr
Recirculation, 15.4×10^4 gpm
Stack Gas: 5.4×10^4 μ Ci/sec

Description of Occurrence

On Tuesday, February 6, 1979, at approximately 0944 hours, while performing the "isolation condenser automatic actuation test and calibration", the RE-15B trip point was found to be less conservative than that specified in the Technical Specifications. Surveillance tests on the high reactor pressure switches for the isolation condenser systems revealed the following data:

<u>Pressure Switch Designation</u>	<u>Desired Setpoint (Head Correction Inc.)</u>	<u>As Found</u>	<u>As Left</u>
RE-15A	1068	1068	1068
RE-15B	1068	1070	1068
RE-15C	1066	1065	1065
RE-15D	1066	1066	1066

Apparent Cause of Occurrence

Instrument repeatability.

Analysis of Occurrence

RE-15B pressure switch would have actuated but at a pressure 2 psig greater than its prescribed value of 1068 psig. The only safety significance of this event was the loss of redundancy in the pressure switch actuation at the prescribed setpoint.

Corrective Action

Immediate corrective action was to reset RE-15B to trip at 1068 psig. No further action is contemplated.

Failure Data

Barksdale
Switch #B2T-A12SS
Proof 1800 psi
Adjustable range 50-1200 psi