

## LICENSEE EVENT REPORT

CONTROL BLOCK:                      ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	A	L	J	M	F	1	2	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4	5					
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31					
LICENSEE CODE														LICENSE NUMBER										LICENSE TYPE				CAT 58	

CONT

0	1	1	6	0	5	0	0	0	3	4	8	7	0	4	1	2	7	9	8	0	5	2	9	7	9	9					
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33					
REPORT SOURCE														DOCKET NUMBER										EVENT DATE				REPORT DATE			

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

① In response to IE Bulletin 79-02, Alabama Power Company initiated a program to  
② randomly select and test a sample of anchor bolts installed in Seismic Category 1,  
③ Safety Related 2½" and greater piping systems. Initial results of that program  
④ revealed that statistical sampling would not be sufficient to provide a high  
⑤ probability of greater than 95% anchor bolt reliability. The potential for anchor  
⑥ bolt failures and the resultant possibility of hanger failure were reported to the NRC  
⑦ on 4/12/79 under the potential applicability of Tech. Spec. 6.9.1.8(i). The health  
⑧ and safety of the public is not affected. ⑨

0	9	Z	Z	11	B	12	C	13	S	U	P	O	R	T	14	X	15	Z	16				
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26				
LER NO. REPORT NUMBER		EVENT YEAR		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.	
17		7 9		—		—		0 7 1				—		0 1		T		—		2			
21		22		23		24		25				26		27		28		29		30		31	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER					
A 18		A 19		Z 20		Z 21		0 0 0 0				Y 23		Y 24		A 25		X 9 9 9 9 26					
33		34		35		36		37				40		41		42		43		44			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ⑳

① The anchor bolt testing program has been expanded to include 100% testing and/or  
② analyses of anchors on pipe hangers for those systems or portions of systems required  
③ to meet design basis accidents or required to bring the plant to cold shutdown.  
④ (See Attachment)

1	4																									80	
7	8																									9	
FACILITY STATUS		% POWER				OTHER STATUS				METHOD OF DISCOVERY		DISCOVERY DESCRIPTION										32					
1 5		H 23				0 0 0 0 29				NA		C 31		Test Program										33			
7		8		9		10		11		12		13		14		15		16		17		18		19		20	
ACTIVITY RELEASED		CONTENT		AMOUNT OF ACTIVITY		LOCATION OF RELEASE																		36			
1 6		Z 33		Z 34		NA		NA																		37	
7		8		9		10		11		12		13		14		15		16		17		18		19		20	
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION																		39			
1 7		0 0 0		Z 37		NA																		40			
7		8		9		10		11		12		13		14		15		16		17		18		19		20	
PERSONNEL INJURIES		NUMBER		DESCRIPTION																		41					
1 8		0 0 0		40		NA																		42			
7		8		9		10		11		12		13		14		15		16		17		18		19		20	
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION																		43					
1 9		Z 42		NA																		44					
7		8		9		10		11		12		13		14		15		16		17		18		19		20	
PUBICITY ISSUED		DESCRIPTION																		45							
2 0		N 44		NA																		46					
7		8		9		10		11		12		13		14		15		16		17		18		19		20	

2237 255

7906040283

NRC USE ONLY

68 69 80

917-926

ALABAMA POWER COMPANY  
JOSEPH M. FARLEY NUCLEAR PLANT  
DOCKET NO. 50-348  
ATTACHMENT TO LER 79-021/01T-2

Facility: Joseph M. Farley Unit 1

Report Date: 5/29/79

Event Date: 4/12/79

Identification of Event:

Potential for anchor bolt failures and the resultant possibility of hanger failure in certain systems.

Conditions Prior to Event:

The unit was in mode 6 (refueling).

Description of Event:

In response to IE Bulletin 79-02, Alabama Power Company initiated a program to randomly select and test a sample of anchor bolts installed in Seismic Category 1, Safety Related, 2½ inch and greater piping systems. Initial results of that program revealed that statistical sampling would not be sufficient to provide a high probability of greater than 95% anchor bolt reliability. The potential for anchor bolt failures and the resultant possibility of hanger failure were reported to the NRC on 4/12/79 under the potential applicability of Technical Specification 6.9.1.8(i). Subject bolts were manufactured by Phillips Drill Co., Hilli Fastening Systems Incorporated and Wej-It Corporation.

Designation of Apparent Cause:

Under investigation.

Analysis of Event:

Alabama Power Company initiated a program to randomly select and test a sample of anchor bolts installed in Seismic Category I, Safety Related, 2½ inch and greater piping systems. Initial results of that program revealed that statistical sampling would not be sufficient to provide a high probability of greater than 95% anchor bolt reliability. Also, it has been found that the hanger designers have not had available to them an official transmittal of the revised loads for 281 supports on lines analyzed by Westinghouse. Potential design, documentation and installation deficiencies exist on pipe hangers. The health and safety of the public is not affected.

2237 256

Corrective Action:

The anchor bolt testing program has been expanded to include 100% verification of acceptable anchors on pipe hangers for those systems or portions of systems required to meet design basis accidents and those required to bring the plant to cold shutdown.

This piping includes:

- a. Seismic Category 1; Safety-Related 2-1/2 inch and above.
- b. Seismic Category 1; Safety-Related Class 1 under 2-1/2 inch.
- c. Seismic Category 1; Safety-Related of other classes for which the designer performed detailed analysis.
- d. All piping through containment penetrations.

The systems involved in the above verification include the following.:

1. Component Cooling Water System
2. Service Water System
3. Sampling System
4. Chemical Volume and Control System
5. Residual Heat Removal System
6. Main Steam System
7. Containment Cooling System
8. Reactor Coolant System
9. Emergency Core Cooling System
10. Main Feedwater System
11. Emergency Diesel Generator with Fuel Oil System
12. Gaseous Waste System
13. Post Accident Containment Hydrogen Control System
14. Auxiliary Feedwater System
15. Containment Spray System
16. Condensate Storage Tank

17. Containment Isolation System

18. Main Steam Safety and Relief Valve Systems

The overall scope of the above verification program includes approximately 12,000 anchor bolts.

Engineering design organizations are participating in determining test acceptance criteria which will ensure proper anchor safety margins. Designers will verify the adequacy of Seismic supports or the inadequacies requiring corrective measures. This will include an evaluation concerning the 281 supports on which revised loads were not evaluated. The necessary corrective action will be accomplished on each system to ensure operability.

The results of the verification will be included in the evaluation covering all portions of all Seismic Category I systems required by IE Bulletin 79-02.

A supplemental LER will be submitted when corrective actions required have been identified. Farley Nuclear Plant will not return to power range reactor operation until such time as Alabama Power Company and NRC Region II mutually agree that potential safety questions have been satisfactorily resolved.

Failure Data:

None

2237 258