

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	E	C	P	R	1	2	0	0	-	0	0	0	-	0	0	0	3	4	1	1	1	1	4			5
7	8	LICENSEE CODE						14	15	LICENSE NUMBER						25	26	LICENSE TYPE				30	57	CAT		58		

CON'T

0 1 7 8

REPORT SOURCE L 6 0 5 0 0 0 2 9 8 7 0 4 2 4 7 9 8 0 5 2 3 7 9 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During refueling while performing scheduled inservice inspection a surface linear indi-
0 3 cation was found in weld RAS-CF-13, main steam to "A" and "B" RHR heat exchangers and
0 4 HPCI turbine. (T.S. 3.6.G) This portion of the main steam is isolatable, redundant
0 5 systems were available, and failure of the weld had it propagated through wall could
0 6 have been detected and retained within the secondary containment. This event presented
0 7 no adverse consequences from the standpoint of public health and safety.

0	8																80										
7	8	9	SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE					COMP. SUBCODE		VALVE SUBCODE											
0	9		C	C	11	B	12	C	13	P	I	P	E	X	X	14	C	15	Z	16							
7	8		9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26							
17		LER/RD REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.															
7		9		21		22		23		24		25		26		27		28		29		30		31		32	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER											
B	18	Z	19	Z	20	Z	21	0	0	0	0	N	23		24	A	25	J	0	3	5		26				
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The subject weld had an area of lack of fusion where the defect originated. The lack
1 1 of fusion was only detectable by radiograph when film and source were lined up with the
1 2 angle of the bevel. Material is SA-106 GR-B, 8", Sch. 100. NOP equal to 1040 psig.
1 3 Defect was removed without violating minimum wall thickness. Upon completion of re-
1 4 pairs the weld was reexamined per ASME, Section XI.

FACILITY STATUS (28) 1 5 H 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
 % POWER 0 0 0 29
 OTHER STATUS NA 30
 METHOD OF DISCOVERY B 31
 DISCOVERY DESCRIPTION Inservice Inspection 32

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 Z 33 10 34 NA NA

7 8 9 11 44 45 80

PERSONNEL EXPOSURES

NUMBER		TYPE	DESCRIPTION
1	7	00	(37) Z (38) NA (39)

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	NA

LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION
1 9 Z (42) NA 2337 215

PUBLICITY
ISSUED DESCRIPTION
2 0 N 44 NA
7 8 9 10 68 69 80
NRC USE ONLY

NAME OF PREPARER Paul F. Doan

PHONE: 402-825-3811

790608031