

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

03 | reading upscale on the 0-5% scale. It was found that the actual 0% reading was

04 | 18.5% on the 0 - 25% scale. The normal expected reading is <4% on the 0 -5% scale.

05 _____

06 _____

07 Technical Specifications 3.6.6.4, 6.9.1.9b

08 8 9

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | A split rubber hose was found leading from the air sample inlet fitting, allowing

11 | air with a high O₂ concentration to be sampled. The split section of tube was

1 2 cut off and the intact tubing was lubricated and reconnected to the sample fitting.

1 3 The hose was new and in good condition. The O₂ reading returned to its normal

1 4 | level. This is considered an isolated event with no further action required

8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS (1) 5 (2) E (28) % POWER (10) 0 (11) 9 (12) 9 (29) OTHER STATUS (30) NA METHOD OF DISCOVERY (31) A (32) DISCOVERY DESCRIPTION (32) Operator Surveillance

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z 33 Z 34 NA

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES						44	45	
NUMBER			TYPE	DESCRIPTION	(39)			
1	7	0	0	0	(37)	Z	(38) NA	

2348 093

		PERSONNEL INJURIES							
		NUMBER	DESCRIPTION						
1	8	0000	(40)						NA

8	9	11	12			30
LOSS OF OR DAMAGE TO FACILITY		(43)				
TYPE		DESCRIPTION				
1	9	Z	(42)	NA		7906220327

8 9 10		PUBLICITY		ISSUED		DESCRIPTION		NRC USE ONLY	
2	0	N	(44)		NA				

NRC USE ONLY