

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 L O A D 1 0 0 0 - 0 0 0 - 0 0 0 4 1 1 1 1 4 5
 9 14 15 25 26 30 57 CAT 58

0 1 REPORT SOURCE L 6 d 5 0 0 0 2 5 4 7 0 1 1 8 7 9 8 0 3 0 9 7 9 9
 80 81 88 89 94 95 99

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While performing the Drywell Head Flange local leak rate test, it was determined the
 0 3 flange seal gasket had a leak rate in excess of 30 SCFH and possibly in excess
 0 4 of the Technical Specification 4.7.A.2.1.1 limit for double-gasketed seals of
 0 5 36.72 SCFH.

0 6
 0 7
 0 8

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
 S D 11 E 12 B 13 P E N E T R 14 C 15 Z 16
 9 10 11 12 13 18 19 20
 17 LER RO REPORT NUMBER EVENT YEAR 7 9 21 22
 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
 C 18 Z 19 Z 20 Z 21 0 0 0 0 22 N 23 Y 24 N 25 C 3 1 0 26
 33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The probable cause of the excessive leakage was due to gasket wear. On February
 1 1 17, 1979 the flange seal gasket was replaced. A second leak rate test was performed
 1 2 and the corrected leak rate was found to be 0.0 SCFH.

1 3
 1 4

1 5 FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
 H 23 0 0 0 29 NA B 31 Local Leak Rate Test
 8 9 10 11 12 13 44 45 46 80
 1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
 Z 33 Z 34 NA NA
 8 9 10 11 44 45 80

1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
 0 0 0 37 Z 38 NA
 8 9 10 11 12 13 80

1 8 PERSONNEL INJURIES NUMBER DESCRIPTION (41)
 0 0 0 40 NA
 8 9 10 11 12 13 80

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)
 Z 42 NA
 8 9 10 11 12 13 80

2 0 PUBLICITY NUMBER DESCRIPTION (45)
 N 44 NA
 8 9 10 11 12 13 80

7903290090

NRC USE ONLY

G. Tietz

PHONE 309-654-2241, ext. 247