

המחלקה לבריאות הציבור, משרד הבריאות

CONTROL BLOCK.

--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME						LICENSE NUMBER										LICENSE TYPE					EVENT TYPE		
N	C	B	E	P	1	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	3
14						25										30					31 32		

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE						REPORT DATE							
INT		L	L	0	5	0	-	0	3	2	5	1	1	0	5	7	7	1	2	0	2	7	7
57 58		59	60	68						69 74						75 80							

VENT DESCRIPTION

With the reactor at power, in the RUN mode, while performing Periodic Test 11.1.5, ADS subsystem logic system functional test, for an L.C.O. on HPCI, R.H.R. pump 1A would not start. (Technical Specification Section 3.5.A.4)

RO 1-77-97

Noncompliance

SYSTEM CODE	CAUSE CODE	COMPONENT CODE	PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER	Noncompliance Code
C F	A	C K T B R R	A	L 2 0 0	Y
10	11	12 13 14 15 16 17	43	44 45 46 47	48

CAUSE DESCRIPTION

Valve E11-F004A, 1A RHR pump suction valve from the torus, breaker was open and the valve left manually open due to a failed valve operator motor being removed for repair. The cover for the valve operator was left on loosely and the (See attached)

FACILITY STATUS		POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
9	E	10	1 0 0	12	NA	44	B	46	NA
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY				LOCATION OF RELEASE	
9	Z	10	Z	11	NA	44		45	NA

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION
000	2	NA

PERSONNEL INJURIES

NUMBER	DESCRIPTION
000	NA

OFFSITE CONSEQUENCES

NA

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION
2	NA

PUBLICITY

7904060397

ADDITIONAL FACTORS

This is being reported under Technical Specification Section 6.11.2.b(2).

LER CONTINUATION -- RO #1-77-97

Facility: BSEP Unit #1

Event Date 11-5-77

Cause Description:

electrical contacts were exposed to a water leak from the overhead. All contacts were found to be corroded which resulted in a invalid logic signal indicating the valve was shut. The pump logic sensed no suction path available and would not allow the pump to start.

Corrective Action:

The wires associated with the pump suction valve position for the logic to 1A RHR pump were removed and the pump was tested satisfactorily. A caution tag was placed on RHR 1A pump control switch to ensure the operators are aware the suction valve logic input is removed.

Action to Prevent a Recurrence:

Instructors will be sent to the maintenance foreman giving guidance on protecting equipment, which has been left open to the environment, while a portion of the equipment has been removed for repair.