

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 02 03 04 05 06 07 08 09 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

L I C E N S E E V E N T R E P O R T

L I C E N S E C O D E L I C E N S E N U M B E R L I C E N S E T Y P E C A T

CON'T

01 02 03 04 05 06 07 08 09 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

R E P O R T S O U R C E R E P O R T N U M B E R D O C K E T N U M B E R E V E N T D A T E R E P O R T D A T E

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

At 0200 in Mode 1, it was reported that Reactor Building isolation valves CAV-4 and CAV-6 would not close from the Control Room after securing from continuous blowdown on 'A' OTSG. This created an event contrary to Technical Specification 3.6.3.1. Redundancy NA. No effect upon the plant or general public as the manual isolation valves were closed. This is the sixth occurrence of this type reported. Ref: LER's (77-36, 122)(78-14,) (79-37 & 38)

01 02 03 04 05 06 07 08 09 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

S Y S T E M C O D E C A U S E C O D E C A U S E S U B C O D E C O M P O N E N T C O D E C O M P S U B C O D E V A L V E S U B C O D E

S D X Z V A L V E X F D

17 L E R R O R E P O R T N U M B E R E V E N T Y E A R E V E N T M O N T H E V E N T D A Y S E Q U E N T I A L R E P O R T N O . O C C U R R E N C E C O D E R E P O R T T Y P E R E V I S I O N N O .

7 9 1 0 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

A C T I O N T A K E N F U T U R E A C T I O N E F F E C T O N P L A N T S H U T D O W N M E T H O D H O U R S A T T A C H M E N T S U B M I T T E D N R R O F O R M S U S P R I M E C O M P S U P P L I E R C O M P O N E N T M A N U F A C T U R E R

D X Z Z 0 0 1 0 0 Y N A R 3 4 1 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

The cause of this event is attributed to CAV-4 being stuck on its backseat and CAV-6 having insufficient lubrication. CAV-4 was freed from its backseat and CAV-6 was lubricated. Both valves were returned to service at 1530 following satisfactory completion of SP-370.

01 02 03 04 05 06 07 08 09 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

F A C I L I T Y S T A T U S P O W E R O T H E R S T A T U S M E T H O D O F D I S C O V E R Y D I S C O V E R Y D E S C R I P T I O N

C 0 2 5 N A A Operator Observation

A C T I V I T Y C O N T E N T R E L E A S E D O R R E L E A S E A M O U N T O F A C T I V I T Y L O C A T I O N O F R E L E A S E

Z Z N A

P E R S O N N E L E X P O S U R E S N U M B E R T Y P E D E S C R I P T I O N

0 0 0 3 Z N A

P E R S O N N E L I N J U R I E S N U M B E R D E S C R I P T I O N

0 0 0 0 N A

L O S S O F O R D A M A G E T O F A C I L I T Y T Y P E D E S C R I P T I O N

Z N

P U B L I C I T Y D E S C R I P T I O N

N

NAME OF PREPARER J. Cooper, Jr. PHONE (904) 795-6486

(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

7908310

481

SUPPLEMENTARY INFORMATION

Report No.: 50-302/79-071/03L-0
Facility: Crystal River Unit #3
Report Date: 22 August 1979
Occurrence Date: 1 August 1979

Identification of Occurrence:

Reactor Building isolation valves CAV-4 and CAV-6 inoperable contrary to Technical Specification 3.6.3.1.

Conditions Prior to Occurrence:

Mode 1 power operation (25%)

Description of Occurrence:

At 0200, it was reported that Reactor Building 'A' OTSG sample line isolation valves, CAV-4 and CAV-6, would not close when securing from continuous blowdown. Manual isolation valves CAV-318, 321, 148 and 149 were closed and CAV-4 and CAV-6 were deactivated in the closed position as per the action statement requirements of Technical Specification 3.6.3.1. Maintenance restored operability and CAV-4 and CAV-6 were returned to service.

Designation of Apparent Cause:

The cause of this event is attributed to CAV-4 being stuck on its backseat and CAV-6 having insufficient lubrication.

Analysis of Occurrence:

No effect upon the plant or general public as manual isolation valves CAV 148, 149, 321 and 318 were closed.

Corrective Action:

CAV-4 was freed from its backseat and CAV-6 was lubricated. Both valves were returned to service after satisfactory completion of Quarterly Cycling of Valves Procedure SP-370. Request for Engineering Information 79-7-5 has been written to evaluate this event and provide solutions to prevent recurrence.

Failure Data:

This is the sixth occurrence of this type reported. Ref: LER's (77-36 & 122), (78-14), (79-37 & 38)

/ws

2035 313