

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

U 1 A L J M F 1 2 0 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 37 CAT 38

REPORT
SOURCE

L 6 0 5 0 0 0 3 4 8 7 0 4 2 2 8 1 3 0 5 2 1 8 1 9
60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 At 2210 on 4/22/81, the overtemperature-delta temperature instrumentation loop associ-
0 3 ated with TI412C was declared inoperable upon the operator noting erratic readings on
0 4 the TI412 indicator and receipt of a channel alert alarm. Tech. Spec. 3.3.1.1, in part,
0 5 requires the TI412C instrumentation loop to be operable. Tech. Spec. 3.3.1.1 action
0 6 statement requirements were met. The health and safety of the public were not affected.
0 7

0 8 9

0 9
7 8 9

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
I 11	E 12	G 13	I N S T R U 14	X 15	Z 16

LER/RO REPORT NUMBER	EVENT YEAR	SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION NO.
17	8 1	0 2 2	0 3	L	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
C 18	Z 19	Z 20	Z 21	0 0 0 0	N 23	N 24	N 25	W 1 2 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 This occurrence is attributable to a defective lead-lag card. The defective card was
1 1 replaced and the channel was returned to service at 0510 on 4/23/81 following the
1 2 successful performance of the surveillance test.
1 3

1 4 9

1 5 FACILITY STATUS 29 0 9 8 29 NA 44 METHOD OF DISCOVERY 31 Receipt of alarm 45 46 80

1 6 ACTIVITY CONTENT 33 Z 34 NA 44 AMOUNT OF ACTIVITY 35 NA 45 LOCATION OF RELEASE 36 80

1 7 PERSONNEL EXPOSURES 37 0 0 0 37 Z 38 NA 44 80

1 8 PERSONNEL INJURIES 40 0 0 0 40 NA 44 80

1 9 LOSS OF OR DAMAGE TO FACILITY 42 Z 42 NA 44 80

2 0 PUBLICITY DESCRIPTION 45 N 45 NA 44 80

NAME OF PREPARER W. G. Hairston, III

PHONE: (205)899-5156

8105270095