

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	A	L	B	R	F	3	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5
LICENSEE CODE								LICENSE NUMBER												LICENSE TYPE				CAT		

CON'T	0	1	I	6	0	5	0	0	0	2	9	6	7	0	5	0	6	8	1	3	0	5	2	0	8	1	9
REPORT SOURCE		DOCKET NUMBER												EVENT DATE				REPORT DATE									

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

During normal operation, while performing unit 2 battery discharge test, valve 3-FCV 73-44 was not opened and tagged with a caution order as required by the SI (T.S.3.5.E.1). There was no danger to the health or safety of the public. Redundant systems were available and operable. There were no previous similar events.

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP SUBCODE	VALVE SUBCODE	EVENT YEAR	SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION NO.	ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB	PRIME COMP SUPPLIER	COMPONENT MANUFACTURER
C E	A	A	V A L V E X	C	A	8 1	0 2 0	0 1	T	0	H	G	Z	Z	0 0 0 0	Y	N	N	C 2 5 5

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The SRO did not interpret the procedure to require the unit 3 HPCI discharge valve to be opened. This incident will be covered in retraining. The SI will be revised to require signoff that the HPCI discharge valve be opened on operating units.

FACILITY STATUS	IN POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
E	1 0 0	NA	D	Inspector observed

ACTIVITY CONTENT RELEASED OR RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
Z	NA	NA

PERSONNEL EXPOSURES NUMBER	TYPE	DESCRIPTION
0 0 0	Z	NA

PERSONNEL INJURIES NUMBER	DESCRIPTION
0 0 0	NA

LOSS OF OR DAMAGE TO FACILITY TYPE	DESCRIPTION
Z	NA

PRIORITY	DESCRIPTION
N	NA

NAME OF PREPARER

PHONE

8105270 119

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 81020 Technical Specification Involved 3.5.E.1

Reported Under Technical Specification 6.7.2.A(2)

Date of Occurrence 5/ 6/81 Time of Occurrence 2115 Unit 3

Identification and Description of Occurrence:

HPCI not declared inoperable due to FCV 73-44 being closed contrary to procedure.

Conditions Prior to Occurrence:

Unit 1 refueling outage.

Unit 2 at 98%

Unit 3 at 100%

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Surveillance requirements of T.S. 4.5.E.2 were not satisfied since personnel were not aware HPCI should be declared inoperable.

Apparent Cause of Occurrence:

SRO misinterpreted procedure and did not open HPCI discharge valve.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

Reinstructed personnel. Recurrence control: Revise SI to require signoff that the HPCI discharge valve be opened.

Failure Data:

None

*Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: SA