

UPDATE REPORT - PREVIOUS REPORT DATE 3/24/81

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 T N S N P 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
 7 8 9 14 15 25 26 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CONT
 01 REPORT SOURCE L 6 0 5 0 0 0 3 2 7 7 0 2 2 4 8 1 8 0 5 2 6 8 1 9
 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 With unit 1 in mode 5, the oxygen analyzer used to monitor for an explosive gas mixture
 03 in the waste holdup tank was declared inoperable. Grab samples were taken within four
 04 hours as required by action statement 43 of LCO 3.3.3.10, but the samples were not
 05 analyzed for approximately 12 hours because both gas chromatographs used for this
 06 analysis were inoperable. There was no effect on public health or safety. No previous
 07 occurrences.

08

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
 M C 11 E 12 E 13 I N S T R U 14 E 15 Z 16
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

17 LER/RO REPORT NUMBER 8 1 0 2 8 0 1 T 1
 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The oxygen cell was damaged due to the collection of condensed moisture in the
 11 analyzer. The water was cleared from the lines, the cell was replaced, and the analyzer
 12 was recalibrated and returned to service. Subsequent analysis verified that the
 13 sampled gas was within the acceptable limits. Additional vents will be added prior to
 14 Unit 2 fuel loading to eliminate excessive water collection.

15 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
 G 28 0 0 0 29 NA A 31 Operator observation
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
 Z 33 Z 34 NA NA
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
 0 0 0 37 Z 38 NA
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

18 PERSONNEL INJURIES NUMBER DESCRIPTION
 0 0 0 40 NA
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
 Z 42 NA
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

20 PUBLICITY ISSUED DESCRIPTION
 N 44 NA
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

21

22

23

24

Name of Preparer M. R. Harding/A. M. Wilkey

Phone (615) 842-8317

G. B. Kirk

8105270 174

LER SUPPLEMENTAL INFORMATION

SQRO-50-327/81028, Revision 1 Technical Specification Involved: 3.3.3.10

Reported Under Technical Specification: 6.9.1.12.b

Date of Occurrence: 2/24/81 Time of Occurrence: 1250 CST

Identification and Description of Occurrence:

The oxygen analyzer used to monitor for an explosive gas mixture in the waste holdup tank was declared inoperable when water damaged the oxygen cell. Grab samples were taken as required by action statement 43 of LCO 3.3.3.10, but analysis of the samples was delayed for approximately 12 hours because both gas chromatographs used for the analysis were inoperable.

Conditions Prior to Occurrence:

Unit 1 in mode 5

Apparent Cause of Occurrence:

Condensed moisture collected in the analyzer and damaged the oxygen cell.

Analysis of Occurrence:

Analysis of the gas sample was delayed until a loan unit could be obtained from the Power Operations Training Center. Subsequent analysis verified that the sampled gas was within technical specification limits.

Corrective Action:

A design modification will be implemented prior to fuel loading of Unit 2 to install additional low-point vents to eliminate the collection of excessive water in the lines connected to the analyzer.