

# LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | A | L | J | M | F | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

REPORT SOURCE | L | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 4 | 7 | 0 | 4 | 2 | 1 | 8 | 1 | 3 | 0 | 5 | 2 | 0 | 8 | 1 | 9  
34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58  
 DOCKET NUMBER EVENT DATE REPORT DATE

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 0112 on 4/21/81, the containment atmosphere particulate and gaseous radioactivity  
 0 3 | monitoring systems (R11 and R12 respectively) were declared inoperable when the inboard  
 0 4 | pump tripped. Tech. Spec. 3.4.7.1 requires R11 and R12 to be operable. Tech. Spec.  
 0 5 | 3.4.7.1 action statement requirements were met. The health and safety of the general  
 0 6 | public were not affected by this occurrence.  
 0 7 |  
 0 8 |  
 0 9 |

SYSTEM CODE | B | B | 11 | CAUSE CODE | D | 12 | CAUSE SUBCODE | Z | 13 | COMPONENT CODE | Z | Z | Z | Z | Z | Z | 14 | COMP SUBCODE | Z | 15 | VALVE SUBCODE | Z | 16 |  
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
 EVENT YEAR | 8 | 1 | SEQUENTIAL REPORT NO. | 0 | 0 | 7 | OCCURRENCE CODE | 0 | 3 | REPORT TYPE | L | REVISION NO. | 0 |  
21 22 23 24 25 26 27 28 29 30 31 32  
 LER NO. REPORT NUMBER | 8 | 1 | ACTION TAKEN | E | 18 | FUTURE ACTION | Z | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | ATTACHMENT SUBMITTED | Y | 23 | NPRO- FORM SUB. | N | 24 | PRIME COMP. SUPPLIER | Z | 25 | COMPONENT MANUFACTURER | Z | 9 | 9 | 9 |  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

## CAUSE DESCRIPTION AND CORRECTIVE ACTION (27)

1 0 | This incident is attributable to a procedural deficiency. The inboard pump tripped due  
 1 1 | to a flow control valve not being lock-wired in the correct position. Upon discovery of  
 1 2 | the condition, the parallel pump was started and R11 and R12 were returned to service  
 1 3 | at 0145 on 4/21/81. Subsequently the flow control valve was lock-wired in the correct  
 1 4 | flow control position, inboard pump repaired and the surveillance test procedure

FACILITY STATUS | G | 28 | % POWER | 0 | 0 | 0 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | A | 31 | DISCOVERY DESCRIPTION | Operator observation | 32 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
 ACTIVITY RELEASED OF RELEASE | Z | 33 | CONTENT | Z | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36 |  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58  
 PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | NA | 39 |  
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
 PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41 |  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58  
 LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43 |  
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
 PUBLICITY ISSUED | N | 44 | DESCRIPTION | NA | 45 |  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58  
 NRC USE ONLY

NAME OF PREPARER W. G. Hairston, III

PHONE: (205) 899-5156

8105270 386

LER 81-007/03L-0 . . . continued

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

modified to require lock-wiring the flow control valve in the correct position.