

LIC 'ISEE EVENT REPORT

| | | | | | | | | | | | | | | | | | | | |
|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|
| CONTROL BLOCK: 1 | | | | | | | | | | (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) | | | | | | | | | |
| M A P P S 1 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 | | | | | | | | | | LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 58 | | | | | | | | | |
| CON'T | | | | | | | | | | REPORT SOURCE L 0 5 0 - 0 2 9 3 7 0 4 1 4 8 1 8 0 5 1 8 8 1 9 | | | | | | | | | |
| EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 | | | | | | | | | | On April 14, 1981 at approximately 2145 hours while performing surveillance test | | | | | | | | | |
| number 8.M.2-2.2.1 entitled "Recirculation System Δ P", pressure instrument 261-39B | | | | | | | | | | was determined to be inoperable. This instrument is one of four channels which | | | | | | | | | |
| contribute to each loop selection logic section of the LPCI mode of the RHR system. | | | | | | | | | | While pressurizing the instrument the indicating needle went beyond its mechanical | | | | | | | | | |
| stop resulting in the inability of the instrument to respond. The instrument was | | | | | | | | | | immediately repaired & returned to service. This was an isolated event. | | | | | | | | | |
| SYSTEM CODE S F 11 | | | | | | | | | | CAUSE CODE A 12 | | | | | | | | | |
| CAUSE SUBCODE B 13 | | | | | | | | | | COMPONENT CODE I N S T R U 14 | | | | | | | | | |
| COMP. SUBCODE S 15 | | | | | | | | | | VALVE SUBCODE Z 16 | | | | | | | | | |
| EVENT YEAR 8 1 | | | | | | | | | | SEQUENTIAL REPORT NO. 0 1 4 | | | | | | | | | |
| OCCURRENCE CODE 0 3 | | | | | | | | | | REPORT TYPE L | | | | | | | | | |
| REVISION NO. 0 | | | | | | | | | | ACTION TAKEN B 18 Z 19 | | | | | | | | | |
| EFFECT ON PLANT Z 20 | | | | | | | | | | SHUTDOWN METHOD Z 21 | | | | | | | | | |
| HOURS 0 0 0 0 | | | | | | | | | | ATTACHMENT SUBMITTED N 23 | | | | | | | | | |
| NPR-4 FORM SUB. N 24 | | | | | | | | | | PRIME COMP. SUPPLIER N 25 | | | | | | | | | |
| COMPONENT MANUFACTURER I 2 0 4 26 | | | | | | | | | | CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27 | | | | | | | | | |
| This instrument problem resulted from a technician error in judgement during the | | | | | | | | | | performance of the above surveillance test. To preclude recurrence of this type of | | | | | | | | | |
| event the technician was immediately instructed as to the proper methods to use in | | | | | | | | | | the performance of this test. | | | | | | | | | |
| FACILITY STATUS E 28 | | | | | | | | | | % POWER 1 0 0 29 | | | | | | | | | |
| OTHER STATUS N.A. 30 | | | | | | | | | | METHOD OF DISCOVERY B 31 | | | | | | | | | |
| DISCOVERY DESCRIPTION 32 | | | | | | | | | | Routine Surveillance Testing | | | | | | | | | |
| ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 | | | | | | | | | | AMOUNT OF ACTIVITY 35 | | | | | | | | | |
| LOCATION OF RELEASE 36 | | | | | | | | | | N.A. | | | | | | | | | |
| PERSONNEL EXPOSURES NUMBER 0 0 0 37 | | | | | | | | | | TYPE 38 | | | | | | | | | |
| DESCRIPTION 39 | | | | | | | | | | N.A. | | | | | | | | | |
| PERSONNEL INJURIES NUMBER 0 0 0 40 | | | | | | | | | | DESCRIPTION 41 | | | | | | | | | |
| N.A. | | | | | | | | | | LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 | | | | | | | | | |
| DESCRIPTION 43 | | | | | | | | | | N.A. | | | | | | | | | |
| PUBLICITY ISSUED N 44 | | | | | | | | | | DESCRIPTION 45 | | | | | | | | | |
| N.A. | | | | | | | | | | NRC USE ONLY | | | | | | | | | |
| NAME OF PREPARER Mr. M. Thomas McLoughlin | | | | | | | | | | PHONE: 617-746-7900 | | | | | | | | | |

8105280173