

**LICENSEE EVENT REPORT**

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	2	1	7	0	4	2	6	8	1	8	0	5	2	1	8	1	9
60	61									68	69						74	75						80
DOCKET NUMBER											EVENT DATE						REPORT DATE							

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On 4-26-81, with Unit 1 shutdown and Unit 2 operating at 99% power, 1B diesel generator surveillance revealed that the standby service water system would not deliver rated flow. Plant service water could not be supplied to 1B DG within 8 hours due to a valve malfunction; thus, 1B DG was declared inoperable. Refueling operations were stopped. This is not a repetitive occurrence. There were no effects on public health or safety due to this event.

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
		W	A	X	Z	P	U	M	P	X	X	B	Z		
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.					
23	24	25	26	27	28	29	30	31	32	33	34				
17	18	19	20	21	22	23	24	25	26	27	28				
		8	1	0	2	0	3	L	0						
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED					
35	36	37	38	39	40	41	42	43	44	45	46				
X	X	Z	Z	0	0	Y	N	A	J	1	0				
18	19	20	21	22	23	24	25	26	27	28	29				

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The system's inability to deliver rated flow is under investigation at  
11 the present time. The valve was repaired and successfully retested and  
12 DG 1B was made operable on plant service water. The system will be ret-  
13 urned to an operable status prior to Unit 1 startup. An update report  
14 will be submitted.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				
1	5	H	28	0	0	0	29	NA	B	31	Performed Surveillance Test	32
7	8	9	10	11	12	13	14	15	16	17	18	19
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE						
1	6	Z	33	Z	34	NA		NA				
7	8	9	10	11	12	13	14	15	16	17	18	19
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION						
1	7	0	0	0	37	Z	38	NA				
7	8	9	10	11	12	13	14	15	16	17	18	19
PERSONNEL INJURIES		NUMBER		DESCRIPTION								
1	8	0	0	0	40			NA				
7	8	9	10	11	12	13	14	15	16	17	18	19
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION								
1	9	Z	42			NA						
7	8	9	10	11	12	13	14	15	16	17	18	19
PUBLICITY		ISSUED		DESCRIPTION								
2	0	N	44			NA						
7	8	9	10	11	12	13	14	15	16	17	18	19

NAME OF PREPARED C. L. Coggin, Supt. Plt. Eng. Serv. PHONE 912-367-7851

LER #: 50-321/1981-035  
Licensee: Georgia Power Company  
Facility Name: Edwin I. Hatch  
Docket #: 50-321

Narrative Report  
for LER 50-321/1981-035

On 4-26-81, with Unit 1 shutdown for a refueling/torus modification outage and Unit 2 operating at 99% power while performing surveillance test HNP-2-3801 "Diesel Generator Manual Start" on 1B diesel generator, it was determined that standby service water system would not deliver rated flow. Diesel generator 1B was declared inoperable 8 hours later when plant service water could not be lined up to the diesel generator while performing HNP-1-3181 section G, "Plant Service Water Pump Auto Function Operability", due to a valve (1P41-F402A) malfunction. Valve 1P41-F402A connects the standby service water system to Unit 1 division 1 service water. Unit 2 performed Tech Specs 4.8.1.1.1.a and 4.8.1.1.2.a.4 within 1 hour since 3 DGs were not operable as required by Tech Specs 3.8.1.1.b. Unit 1 already had 1C DG inoperable; thus, refueling operations were stopped when DG 1B was declared inoperable. Unit 1 Tech Specs 3.9.1 required 2 DGs operable during refueling. This is not a repetitive occurrence. There were no effects on public health or safety due to this event. Further investigation revealed stripped gears in valve 1P41-F402A. The valve was repaired. HNP-1-3181 section G performed successfully and DG 1B declared operable.

Investigation is underway to find reason for inadequate flow in standby service water system. The standby service water system will be made operable prior to Unit 1 startup following the outage. An update report will be submitted.