

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONT

REPORT SOURCE

80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99

0 1

L 6 0 5 0 0 0 2 5 9 7 0 5 0 1 8 1 8 0 6 0 5 8 1 9

DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

| | | | | | | | | | | | | | | | | | |
|-------------------------|--|---|--|------------------------------|--|----------------------------------|--|----------------------|--|------------------------------|--|--------------------------|--|------------------------------|--|--------------------------------------|--|
| SYSTEM CODE A B 11 | | CAUSE CODE A 12 | | CAUSE SUBCODE X 13 | | COMPONENT CODE Z Z Z Z Z Z 14 | | | | COMP. SUBCODE Z 15 | | VALVE SUBCODE Z 16 | | | | | |
| EVENT YEAR 8 1 21 22 | | SEQUENTIAL REPORT NO. 0 1 6 24 25 26 | | OCCURRENCE CODE 0 1 28 29 | | REPORT TYPE T 30 | | REVISION NO. 1 32 | | | | | | | | | |
| ACTION TAKEN G 18 | | FUTURE ACTION Z 19 | | EFFECT ON PLANT Z 20 | | SHUTDOWN METHOD Z 21 | | HOURS 0 0 0 22 | | ATTACHMENT SUBMITTED Y 23 | | NPRD-4 FORM SUB. N 24 | | PRIME COMP. SUPPLIER Z 25 | | COMPONENT MANUFACTURER Z 9 9 9 26 | |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

A horizontal number line is shown, starting at 0 and ending at 30. There are tick marks every 1 unit, with labels at 0, 10, 20, and 30. Above the number 9, there is a small box containing the numbers 1 and 4.

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 2 33 10 34

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

NA

| PERSONNEL INJURIES | | DESCRIPTION | |
|--------------------|-------------|-------------|-------------|
| NUMBER | DESCRIPTION | NUMBER | DESCRIPTION |
| 0000 | NA | | |

PUBLICITY
 ISSUED (N) (44) DESCRIPTION (45) NA
 NRC USE ONLY

NAME OF PREPARER

PHONE

8106090 537

090 217-926

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 81016 R1 Technical Specification Involved 3.11.A.1.b

Reported Under Technical Specification 6.7.2.a(2)

Date of Occurrence 5/8/81 Time of Occurrence 1550 Unit 1, 2, and 3

Identification and Description of Occurrence:

Power (120V AC preferred) lifted to fire pump auto-initiation. The exact duration the circuit had been inoperable could not be determined. However, it is probable that the wiring was removed during the modification activity, making the duration 2 weeks or less.

Conditions Prior to Occurrence:

Unit 1 refueling outage.

Unit 2 at 99%.

Unit 3 at 100%.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Reterminated power supply.

Apparent Cause of Occurrence:

Wiring was removed from terminal points in main relay panel 52 resulting in the interruption of power to the fire pump auto-start circuit. Although it could not definitely be determined how the wiring was removed, it is suspected that the wires were removed during performance of a modification in the panel.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

Replaced permanent wiring immediately. Precautions have been added to the workplan requiring the electricians to consult the cognizant engineer prior to removing any existing wiring.

Failure Data:

None

*Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: SA