

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK										(1)																													
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40
A L B R F 3										0 0 - 0 0 0 0 0 - 0 0										4 1 1 1 1										4									
LICENSEE CODE										LICENSE NUMBER										LICENSE TYPE										SY CAT SR									

41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
L										0 5 0 0 0 2 9 6										0 5 0 7 8 1										0 6 0 3 8 1									
DOCKET NUMBER										EVENT DATE										REPORT DATE																			

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

During routine startup, 3B recirculation pump M/G set field breaker indicating light was out. The trip coil was found open and the M/G set was removed from service for maintenance. This resulted in operation with only one recirculation loop. (T.S. 3.6.F.1) The M/G set and pump were off for 20 minutes to replace field breaker. There was no danger to the health or safety of the public. There were no previous similar events.

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP SUBCODE		VALVE SUBCODE			
C	B	E	A	C	K	T	B	R	K	A	Z				
EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
8	1	0	2	1	0	3	L		0						
ACTION FACTOR		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB		PRIME COMP SUPPLIER		COMPONENT MANUFACTURER	
A	Z	Z	Z	0	0	0	0	Y	Y	L	G	G	8	0	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

M/G set field breaker trip coil (General Electric, 230/250 vdc, type 6275081G30, was open. Breaker was replaced and successfully tested. This is considered a random failure, and no other recurrence control is required.

FACILITY STATUS		POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
C	0	6	1	NA	A	Operator observed			
ACTIVITY RELEASED		CONTENT		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
Z	Z	NA	NA						
INCIDENT NUMBER		TYPE		DESCRIPTION					
0	0	0	Z	NA					
INCIDENT NUMBER		DESCRIPTION							
0	0	0	NA						
LONG TERM DAMAGE TO FACILITY		DESCRIPTION							
Z	NA								
PROBABLE CAUSE		DESCRIPTION							
N	NA								

POOR ORIGINAL

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 81021 Technical Specification Involved 3.6.F.1

Reported Under Technical Specification 6.7.2.b(2)

Date of Occurrence 5/7/81 Time of Occurrence 1535 Unit 3

Identification and Description of Occurrence:

Removed 3B reactor recirculation pump from service to repair motor generator field breaker trip circuit.

Conditions Prior to Occurrence:

Unit 1 refueling outage.

Unit 2 at 37%

Unit 3 at 61%

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None required

Apparent Cause of Occurrence:

Motor generator set field trip coil was open.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

Replaced Breaker, tested and returned pump to service.

Failure Data:

None

*Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: JLH