

LICENSEE EVENT REPORT

CONTROL BLOCK:

1	2	3	4	5	6
---	---	---	---	---	---

 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1
---	---

N	J	S	G	S	1
---	---	---	---	---	---

2	0	0	-	0	0	0	0	0	0	-	0	0
---	---	---	---	---	---	---	---	---	---	---	---	---

3	4	1	1	1	1
---	---	---	---	---	---

4	5
---	---

7 8 9 14 15 25 26 57 CAT 58CON'T

0	1
---	---

 REPORT SOURCE

L	6	0	5	0	0	0	2	7	2
---	---	---	---	---	---	---	---	---	---

7	0	5	1	2	8	1
---	---	---	---	---	---	---

8	0	6	0	8	8	1
---	---	---	---	---	---	---

9

7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2
---	---

 At 1120 hours on May 12, 1981, Action Statement 3.6.2.3 was entered due to

0	3
---	---

 13 Containment Fan Coil Unit not being capable of a shift from low service water flow

0	4
---	---

 to high service water flow. This occurrence constitutes operation in a degraded mode

0	5
---	---

 IAW Technical Specification 6.9.1.9b.

0	6
---	---

0	7
---	---

0	8
---	---

0	9
---	---

S	C
---	---

11

E

12

B

13

V	A	L	V	E	X
---	---	---	---	---	---

14

A

15

G

16

7 8 9 10 11 12 13 18 19 20

17

 LER RO REPORT NUMBER

8	1
---	---

21

22

0	4	6
---	---	---

24

26

27

0	3
---	---

28

29

L

30

31

0

32

21 22 23 24 26 27 28 29 30 31 32ACTION TAKEN

A

18

 FUTURE ACTION

Z

19

 EFFECT ON PLANT

Z

20

 SHUTDOWN METHOD

Z

21

 HOURS

0	0	0	0
---	---	---	---

22

 ATTACHMENT SUBMITTED

y

23

 NPD-4 FORM SUB

y

24

 PRIME COMP. SUPPLIER

L

25

 COMPONENT MANUFACTURER

M	1	2	0
---	---	---	---

26

33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0
---	---

 Investigation disclosed that valve 13SW65 would not function due to the stem being

1	1
---	---

 separated from the actuator. Separation was caused by a cracked trunnion block plug.

1	2
---	---

 The trunnion block plug was replaced. Additional valve internals were replaced as a

1	3
---	---

 preventive maintenance measure. 13 Containment Fan Coil Unit was tested satisfactorily.

1	4
---	---

 Action Statement 3.6.2.3 was terminated at 2335 hours on May 13, 1981.

1	5
---	---

E

28

0	9	9
---	---	---

29

N/A

30

A

31

 Operator Observation

32

7 8 9 10 11 12 13 44 45 46 80

1	6
---	---

Z

33

Z

34

N/A

35

N/A

36

7 8 9 10 11 12 44 45 46 80

1	7
---	---

0	0	0
---	---	---

37

Z

38

N/A

39

7 8 9 10 11 12 13 44 45 46 80

1	8
---	---

0	0	0
---	---	---

40

N/A

41

7 8 9 10 11 12 13 44 45 46 80

1	9
---	---

Z

42

N/A

43

7 8 9 10 11 12 44 45 46 80

2	0
---	---

N

44

N/A

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

61

62

63

64

65

66

67

68

69

70

71

72

73

74

75

76

77

78

79

80

7 8 9 10 11 12 13 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

8106150 219 NAME OF PREPARER J. J. Espey PHONE 609-935-0998