

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK:

--	--	--	--	--	--

 (1)

01 | G | A | E | I | H | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

REPORT SOURCE	60	61	DOCKET NUMBER							68	EVENT DATE					74	REPORT DATE					80			
	L	6	0	5	0	0	0	3	2	1	7	0	6	0	5	8	1	8	0	6	2	5	8	1	9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On June 5, 1981, with the reactor in the startup and hot standby mode, while performing HNP-1-3400, RCIC Valve Operability Test, the 1E51-F105 would not open by the control switch. Per Tech Spec 4.5.E.2, the RCIC was declared inoperative. Public health and safety was not affected by this incident. This is a non-repetitive event.

0	7	
---	---	--

08

7 8 9

0 9

SYSTEM CODE

CAUSE CODE

CAUSE SUBCODE

COMPONENT CODE

COMP. SUBCODE

VALVE SUBCODE

9 10 11 12 13 14 15 16 17 18 19 20

C E 11

E 12

A 13

R E L A Y X 14

A 15

Z 16

LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.												
17		21	22	23	24	25	26	27	28	29	30	31	32									
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FO M SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER						
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50					
B	18	Z	19	Z	20	Z	21	0	0	0	0	Y	23	N	24	N	25	G	0	8	0	26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of the valve not opening was due to a relay cover binding on
11 a logic relay. The binding physically held the relay up and would not
12 allow continuity through the open circuit of the valve. The relay cover
13 was installed correctly and the valve functionally tested with
14 satisfactory results.

7 8 9
FACILITY STATUS (28) 1 5 C
% POWER 0 0 1 (29)
OTHER STATUS (30) NA
METHOD OF DISCOVERY (31) B
DISCOVERY DESCRIPTION (32) Operator observation

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)
1 6 Z 33 Z 34 NA
LOCATION OF RELEASE (36)
NA

PERSONNEL EXPOSURES			DESCRIPTION	
NUMBER	TYPE			
17	000	(37) Z	(38)	NA

7		8		9		11		12		13	
PERSONNEL INJURIES											
NUMBER						DESCRIPTION					
1	8	0	0	0	(40)	NA					

7	8	9	11	12
LOSS OF OR DAMAGE TO FACILITY			(43)	
TYPE			DESCRIPTION	
1	9	Z	(42)	NA

7 8 9 10
PUBLICITY
ISSUED DESCRIPTION (45)
2 0 N 14 NA

NAME OF PREPARER R. T. Nix, Supt. of Maint.

PHONE: 912-367-7781

LER No.: 50-321/1981-049
Licensee: Georgia Power Company
Facility: Edwin I. Hatch
Docket No.: 50-321

On June 5, 1981, with the reactor in the startup and hot standby mode, HNP-1-3402, RCIC Valve Operability Test, was being performed. During this test, 1E51-F105, RCIC Outboard Turbine Exhaust Vacuum Breaker Valve, failed to operate. Per Tech Spec 4.5.E.2, RCIC was then declared inoperative.

It was discovered after thorough investigation, the valve failure was due to a protective cover binding on a logic relay. The relay is located in a panel in the control room and during the recent refueling outage, extensive work was performed in this panel. During this work, it was determined that the relay cover was accidentally bumped or knocked off and improperly replaced thus causing the relay to bind and fail to operate. The relay cover was removed, the relay was inspected, cleaned and the protective cover was reinstalled correctly. The valve was then functionally tested and passed with satisfactory results. Public health and safety was not affected by this incident and this is not a repetitive occurrence. A generic review reveals no inherent problems of this type.