

LICENSEE EVENT REPORT

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 ALBRF1 7 00-000000-000 3 4 1 1 1 1 4 5
LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 48

01 01 L 6 050000259 7 0 5 2 7 8 1 8 0 6 2 5 8 1 9
DOCKET NUMBER 61 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 With units 1 and 2 shut down, and unit 3 at 100% steady state, wind direction channel
03 XR-90-102-2 (elevation 33 feet) failed. (See T.S. 3.3.I) The wind direction channel
04 is common to units 1, 2, and 3. There was no danger to the health or safety of the
05 public. Redundant systems were available and operable. There were no previous
06 similar events.

01 01 SYSTEM CODE 02 01 CAUSE CODE 03 01 CAUSE SUBCODE 04 01 COMPONENT CODE 05 01 COMP. SUBCODE 06 01 VALVE SUBCODE
07 01 EVENT YEAR 08 01 SEQUENTIAL REPORT NO. 09 01 OCCURRENCE CODE 10 01 REPORT TYPE 11 01 REVISION NO.
02 01 ACTION TAKEN 03 01 EFFECT ON PLANT 04 01 SHUTDOWN METHOD 05 01 HOURS 06 01 ATTACHMENT SUBMITTED 07 01 NPRO-4 FORM SUB 08 01 PRIME COMP. SUPPLIER 09 01 COMPONENT MANUFACTURER
01 01 02 01 03 01 04 01 05 01 06 01 07 01 08 01 09 01 10 01 11 01 12 01 13 01 14 01 15 01 16 01 17 01 18 01 19 01 20 01 21 01 22 01 23 01 24 01 25 01 26 01 27 01 28 01 29 01 30 01 31 01 32 01 33 01 34 01 35 01 36 01 37 01 38 01 39 01 40 01 41 01 42 01 43 01 44 01 45 01 46 01 47 01

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

01 01 In line fuse in the Esterline Angus recorder blew during an electrical storm. The
02 fuse was replaced and the system was returned to service within 24 hours. This is
03 considered a random failure and no recurrence control is required.

01 01 FACILITY STATUS 02 01 POWER 03 01 OTHER STATUS 04 01 METHOD OF DISCOVERY 05 01 DISCOVERY DESCRIPTION 06 01 LOCATION OF RELEASE
01 01 02 01 03 01 04 01 05 01 06 01 07 01 08 01 09 01 10 01 11 01 12 01 13 01 14 01 15 01 16 01 17 01 18 01 19 01 20 01 21 01 22 01 23 01 24 01 25 01 26 01 27 01 28 01 29 01 30 01 31 01 32 01 33 01 34 01 35 01 36 01 37 01 38 01 39 01 40 01 41 01 42 01 43 01 44 01 45 01 46 01 47 01

01 01 PERSONNEL EXPOSURES 02 01 TYPE 03 01 DESCRIPTION 04 01 PERSONNEL INJURIES 05 01 NUMBER 06 01 DESCRIPTION
01 01 02 01 03 01 04 01 05 01 06 01 07 01 08 01 09 01 10 01 11 01 12 01 13 01 14 01 15 01 16 01 17 01 18 01 19 01 20 01 21 01 22 01 23 01 24 01 25 01 26 01 27 01 28 01 29 01 30 01 31 01 32 01 33 01 34 01 35 01 36 01 37 01 38 01 39 01 40 01 41 01 42 01 43 01 44 01 45 01 46 01 47 01

01 01 LOSS OF OR DAMAGE TO FACILITY 02 01 TYPE 03 01 DESCRIPTION 04 01 PERSONNEL INJURIES 05 01 NUMBER 06 01 DESCRIPTION
01 01 02 01 03 01 04 01 05 01 06 01 07 01 08 01 09 01 10 01 11 01 12 01 13 01 14 01 15 01 16 01 17 01 18 01 19 01 20 01 21 01 22 01 23 01 24 01 25 01 26 01 27 01 28 01 29 01 30 01 31 01 32 01 33 01 34 01 35 01 36 01 37 01 38 01 39 01 40 01 41 01 42 01 43 01 44 01 45 01 46 01 47 01

01 01 FACILITY 02 01 TYPE 03 01 DESCRIPTION 04 01 PERSONNEL INJURIES 05 01 NUMBER 06 01 DESCRIPTION
01 01 02 01 03 01 04 01 05 01 06 01 07 01 08 01 09 01 10 01 11 01 12 01 13 01 14 01 15 01 16 01 17 01 18 01 19 01 20 01 21 01 22 01 23 01 24 01 25 01 26 01 27 01 28 01 29 01 30 01 31 01 32 01 33 01 34 01 35 01 36 01 37 01 38 01 39 01 40 01 41 01 42 01 43 01 44 01 45 01 46 01 47 01

01 01 FACILITY 02 01 TYPE 03 01 DESCRIPTION 04 01 PERSONNEL INJURIES 05 01 NUMBER 06 01 DESCRIPTION
01 01 02 01 03 01 04 01 05 01 06 01 07 01 08 01 09 01 10 01 11 01 12 01 13 01 14 01 15 01 16 01 17 01 18 01 19 01 20 01 21 01 22 01 23 01 24 01 25 01 26 01 27 01 28 01 29 01 30 01 31 01 32 01 33 01 34 01 35 01 36 01 37 01 38 01 39 01 40 01 41 01 42 01 43 01 44 01 45 01 46 01 47 01

NAME OF PREPARED

PHONE

8106300 193

POOR ORIGINAL

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 81026 Technical Specification Involved 3.3.I

Reported Under Technical Specification 6.7.2.b (2) *Date due NRC: 6/26/81

Date of Occurrence 5/27/81 Time of Occurrence 0430 Unit 1, 2, and 3

Identification and Description of Occurrence:
Wind direction channel at 33 feet failed (XR90-102-2).

Conditions Prior to Occurrence:
Unit 1 refueling outage

Unit 2 modification outage

Unit 3 at 100%

Action specified in the Technical Specification Surveillance Requirements met
due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:
Wind direction channel at 33 feet - fuse blew in line to recorder during an electrical storm.

Analysis of Occurrence:
There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:
Replaced fuse and the channel returned to service within 24 hours. This is considered a random event and no recurrence control is required.

Failure Data: None

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: *All*

POOR ORIGINAL

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[illegible]

LER SUPPLEMENTAL INFORMATION

BERO-50- 259 / 81026 Technical Specification Involved 3.3.1

Reported Under Technical Specification 6.7.2.b (2) *Date due NRC: 6/26/81

Date of Occurrence 5/27/81 Time of Occurrence 0430 Unit 1, 2, and 3

Identification and Description of Occurrence:
Wind direction channel at 33 feet failed (XR90-102-2).

Conditions Prior to Occurrence:
Unit 1 refueling outage

Unit 2 modification outage

Unit 3 at 100%

Action specified in the Technical Specification Surveillance Requirements met
due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:
Wind direction channel at 33 feet - fuse blew in line to recorder during an electrical storm.

Analysis of Occurrence:
There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:
Replaced fuse and the channel returned to service within 24 hours. This is considered a random event and no recurrence control is required.

Failure Data: None

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: ALL

POOR ORIGINAL