

LICENSEE EVENT REPORT

CONTROL BLOCK:										(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)									
<div> <div>01</div> <div>MIPAL1</div> <div>200-000000-00</div> <div>341111</div> <div>4</div> <div>5</div> </div>										<div> <div>LICENSEE CODE</div> <div>LICENSE NUMBER</div> <div>LICENSE TYPE</div> <div>CAT</div> </div>									
<div> <div>01</div> <div>REPORT SOURCE</div> <div>6050002557052781</div> <div>8062581</div> <div>9</div> </div>										<div> <div>DOCKET NUMBER</div> <div>EVENT DATE</div> <div>REPORT DATE</div> </div>									
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)																			
<div> <div>02</div> <div>Following a routine test of annunciator panels, the alarms would not</div> </div>																			
<div> <div>03</div> <div>reset. The alarms (fire detection) are required to be operable per TS</div> </div>																			
<div> <div>04</div> <div>3.22.1.1. Instruments 1 through 5 of Table 3.22.1 were affected. A</div> </div>																			
<div> <div>05</div> <div>fire watch was established IAW requirements of 3.22.1. Event reportable</div> </div>																			
<div> <div>06</div> <div>per TS 6.9.2.B2. No threat to public health or safety.</div> </div>																			
<div> <div>07</div> </div>																			
<div> <div>08</div> </div>																			
<div> <div>09</div> <div> <div>SYSTEM CODE</div> <div>CAUSE CODE</div> <div>CAUSE SUBCODE</div> <div>COMPONENT CODE</div> <div>COMP. SUBCODE</div> <div>VALVE SUBCODE</div> </div> </div>																			
<div> <div>17</div> <div> <div>LER/RO REPORT NUMBER</div> <div>EVENT YEAR</div> <div>SEQUENTIAL REPORT NO.</div> <div>OCCURRENCE CODE</div> <div>REPORT TYPE</div> <div>REVISION NO.</div> </div> </div>																			
<div> <div> <div>ACTION TAKEN</div> <div>FUTURE ACTION</div> <div>EFFECT ON PLANT</div> <div>SHUTDOWN METHOD</div> <div>HOURS</div> <div>ATTACHMENT SUBMITTED</div> <div>NPRD-4 FORM SUB.</div> <div>PRIME COMP. SUPPLIER</div> <div>COMPONENT MANUFACTURER</div> </div> </div>																			
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)																			
<div> <div>10</div> <div>A relay coil failure caused the event. The relay was repaired and</div> </div>																			
<div> <div>11</div> <div>operability restored within 9 hours.</div> </div>																			
<div> <div>12</div> </div>																			
<div> <div>13</div> </div>																			
<div> <div>14</div> </div>																			
<div> <div>15</div> <div> <div>FACILITY STATUS</div> <div>% POWER</div> <div>OTHER STATUS</div> <div>METHOD OF DISCOVERY</div> <div>DISCOVERY DESCRIPTION</div> </div> </div>																			
<div> <div>16</div> <div> <div>ACTIVITY RELEASED OF RELEASE</div> <div>AMOUNT OF ACTIVITY</div> <div>LOCATION OF RELEASE</div> </div> </div>																			
<div> <div>17</div> <div> <div>PERSONNEL EXPOSURES</div> <div>DESCRIPTION</div> </div> </div>																			
<div> <div>18</div> <div> <div>PERSONNEL INJURIES</div> <div>DESCRIPTION</div> </div> </div>																			
<div> <div>19</div> <div> <div>LOSS OF OR DAMAGE TO FACILITY</div> <div>DESCRIPTION</div> </div> </div>																			
<div> <div>20</div> <div> <div>PUBLICITY</div> <div>DESCRIPTION</div> </div> </div>																			
<div> <div>21</div> <div> <div>ISSUED</div> <div>DESCRIPTION</div> </div> </div>																			
<div> <div>22</div> <div> <div>NRC USE ONLY</div> </div> </div>																			

8107080207 810625
PDR ADOCK 05000255
S PDR

12