

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 F L C R P 3 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 1000 1 L 6 0 5 0 - 0 3 0 2 7 1 0 1 0 8 1 8 1 1 0 6 8 1 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

0 2 During performance of shutdown surveillance activities, various reactor protection

0 3 instruments were found out-of-tolerance. These events were not attributed to a specific

0 4 shutdown activity, as required by Reg. Guide 1.16 and, therefore, are reportable as

0 5 being contrary to T.S. 3.3.1.1. There was no effect upon the health or safety of the

0 6 general public. Nine instruments (RC-14A-DPT4 on 10/10/81; RC-14A-DPT1 on 10/11/81;

0 7 RC-14B-DPT4 and RC-14B-DPT1 on 10/13/81; RC-14B-DPT2 on 10/17/81; RC-14B-DPT3 on 10/20/81;

0 8 RC-3B-PT1 and RC-3B-PT2 on 10/26/81; RC-3A-PT1 on 10/27/81) were out-of-tolerance. This

0 9 is the ninth event reported under this Specification.

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
1 A 11 X 12 Z 13 I N S T R U 14 T 15 Z 16

17 LER/RO REPORT NUMBER 8 1 1 21 22 23 24 25 26 27 28 29 30 31 32

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
X 18 Z 19 Z 20 Z 21 0 0 0 0 22 Y 23 N 24 A 25 B 0 4 5 26

0 10 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

0 11 RC-14A-DPT4 had a bellows failure. The bellows was replaced. RC-14A-DPT1, RC-14B-DPT4,

0 12 RC-14B-DPT1, and RC-14B-DPT2, RC-3B-PT1 and RC-3B-PT2, also RC-3A-PT1 failed due to

0 13 instrument drift. RC-14B-DPT3 had a loose test point output terminal. The terminal

0 14 was tightened. All instruments were satisfactorily recalibrated. No further corrective

0 15 action is deemed necessary.

0 15 FACILITY STATUS 1 POWER 2 OTHER STATUS 30 4 METHOD OF DISCOVERY 5 DISCOVERY DESCRIPTION 32
H 28 0 0 0 29 NA B 31 Technician observation

0 16 ACTIVITY CONTENT 7 RELEASED OF RELEASE 8 AMOUNT OF ACTIVITY 35 9 LOCATION OF RELEASE 36
Z 33 Z 34 NA NA

0 17 PERSONNEL EXPOSURES 8 NUMBER 9 TYPE 10 DESCRIPTION 39
0 0 0 37 Z 38 NA

0 18 PERSONNEL INJURIES 8 NUMBER 9 DESCRIPTION 41
0 0 0 40 NA

0 19 LOSS OF OR DAMAGE TO FACILITY 43 8 TYPE 9 DESCRIPTION
Z 42 NA

0 20 PUBLICITY 45 8 ISSUED 9 DESCRIPTION
N 44

8111180239 811106
PDR ADOCK 05000302
S PDR

NAME OF PREPARER Victor A. Hernandez PHONE 904/795-6486
(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

SUPPLEMENTARY INFORMATION

Report No.: 50-302/81-066/03L-0
Facility: Crystal River Unit 3
Report Date: November 6, 1981
Occurrence Date: October 10, 1981
Identification of Occurrence:

Various reactor protection instruments were found out-of-tolerance during shutdown surveillance activities. These events were not attributed to specific shutdown activities as required by Regulatory Guide 1.16, and, therefore, are being reported as contrary to Technical Specification 3.3.1.1.

Conditions Prior to Occurrence:

Mode 6 refueling (0%).

Description of Occurrence:

On October 10, 1981, during performance of SP-112, Calibration of the Reactor Protection System, RC-14A-DPT4 was found out-of-tolerance. On October 11, 1981, during performance of SP-112, RC-14A-DPT1 was found out-of-tolerance. On October 13, 1981, during performance of SP-112, RC-14B-DPT4 and RC-14B-DPT1 were found out-of-tolerance. On October 17, 1981, during performance of SP-112, RC-14B-DPT2 was found out-of-tolerance. On October 20, 1981, during performance of SP-112, RC-14B-DPT3 was found out-of-tolerance. On October 26, 1981, during performance of SP-112, RC-3B-PT1 and RC-3B-PT2 were found out-of-tolerance. On October 27, 1981, during performance of SP-112, RC-3A-PT1 was found out-of-tolerance.

Designation of Apparent Cause:

RC-14A-DPT4 had a bellows failure. The bellows was replaced. RC-14A-DPT1, RC-14B-DPT4, RC-14B-DPT1, and RC-14B-DPT2, RC-3B-PT1, and RC-3B-PT2, and RC-3A-PT1, all failed due to instrument drift. RC-14B-DPT3 had a loose test point output terminal. The terminal was tightened.

Analysis of Occurrence:

There was no effect upon the health or safety of the general public.

Corrective Action:

All instruments were satisfactorily recalibrated. No further corrective action is deemed necessary.

Failure Data:

Nine instruments were found out-of-tolerance. This is the ninth event reported under this Specification.