

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|---|---------------|---|---|---|---|---|----|----|----------------|---|---|---|---|---|----|----|--------------|---|---|---|----|-----------|---|--|---|
| 0 | 1 | N | Y | N | M | P | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | | 5 |
| 7 | 8 | 9 | LICENSEE CODE | | | | | | 14 | 15 | LICENSE NUMBER | | | | | | 25 | 26 | LICENSE TYPE | | | | 30 | 57 CAT 58 | | | |

CON'T

| | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|---------------|---|----|----|---------------|---|---|---|---|---|----|----|------------|---|---|---|----|----|-------------|---|---|---|----|---|---|
| 0 | 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 2 | 0 | 7 | 0 | 6 | 0 | 3 | 8 | 1 | 8 | 0 | 7 | 0 | 2 | 8 | 1 | 9 |
| 7 | 8 | REPORT SOURCE | | 60 | 61 | DOCKET NUMBER | | | | | | 68 | 69 | EVENT DATE | | | | 74 | 75 | REPORT DATE | | | | 80 | | |

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During a refueling outage, while performing local leak rate testing, Reactor

0 3 Building to Torus Vacuum Breaker Balbe 68-08 failed to meet the Tech Spec leak

0 4 rate requirements of <12.9 SCFH.

0 5

0 6

0 7

0 8

| | | | | | | | | | | | | | | | | | | | | | |
|---|---|-------------|---|----|------------|----|----|---------------|---|----|----------------|---|---|---|----|---------------|----|----|---------------|--|----|
| 0 | 9 | S | D | 11 | E | 12 | B | 13 | V | A | L | V | E | X | 14 | B | 15 | C | 16 | | |
| 7 | 8 | SYSTEM CODE | | 9 | CAUSE CODE | | 11 | CAUSE SUBCODE | | 12 | COMPONENT CODE | | | | 13 | COMP. SUBCODE | | 19 | VALVE SUBCODE | | 20 |

17 LER/RO REPORT NUMBER 81 EVENT YEAR 81 SEQUENTIAL REPORT NO. 023 OCCURRENCE CODE 03 REPORT TYPE L REVISION NO. 0

ACTION TAKEN A FUTURE ACTION X EFFECT ON PLANT Z SHUTDOWN METHOD Z HOURS 0000 ATTACHMENT SUBMITTED N NPD-4 FORM SUB N PRIME COMP. SUPPLIER L COMPONENT MANUFACTURER A180

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of this failure is worn seating and packing materials. After mainten-

1 1 ance the valve was successfully local leak rate tested. The site is investigating

1 2 a preventative maintenance program such as periodic replacement of rubber goods

1 3 to preclude further failures of this Allis Chalmers 30" butterfly valve.

1 4

1 5 FACILITY STATUS H % POWER 000 OTHER STATUS NA METHOD OF DISCOVERY B DISCOVERY DESCRIPTION TECHNICIAN OBSERVATION

1 6 ACTIVITY CONTENT RELEASED OF RELEASE Z AMOUNT OF ACTIVITY NA LOCATION OF RELEASE NA

1 7 PERSONNEL EXPOSURES NUMBER 000 TYPE Z DESCRIPTION NA

1 8 PERSONNEL INJURIES NUMBER 000 DESCRIPTION NA

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z DESCRIPTION NA

2 0 PUBLICITY ISSUED N DESCRIPTION NA

8107130438 810702
PDR ADDCK 05000220
S PDR

NRC USE ONLY

NAME OF PREPARER Robert RandallPHONE: (315)343-2110, ext. 1596