



Wisconsin Electric POWER COMPANY
231 WEST MICHIGAN, MILWAUKEE, WISCONSIN 53201

June 5, 1981

Mr. J. G. Keppler, Regional Director
Office of Inspection and Enforcement,
Region III
U. S. NUCLEAR REGULATORY COMMISSION
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

DOCKET NO. 50-266
POINT BEACH NUCLEAR PLANT, UNIT 1
LICENSEE EVENT REPORT NO. 81-005/03L-0

Enclosed is Licensee Event Report No. 81-005/03L-0
(a 30-day report) with an attachment which provides a description
of an event reportable in accordance with Technical Specification
15.6.9.2.B.2, "Conditions leading to operation in a degraded
mode permitted by a limiting condition for operation or plant
shut-down required by a limiting condition for operation."

Very truly yours,

C. W. Fay, Director
Nuclear Power Department

Enclosure

Copy to NRC Resident Inspector

8107140366 810702
PDR ADDCK 05000266
S PDR

JUL 6 1981

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK: [] [] [] [] [] [] (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	W	I	P	B	H	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5			
7	8	9	LICENSEE CODE						14	LICENSE NUMBER										25	26	LICENSE TYPE					30	57 CAT 58				

CON'T

REPORT SOURCE: 01 L 6 0 5 0 0 0 2 6 6 7 0 5 1 5 8 1 8 0 6 0 5 8 1 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[0] [2] On 5-15-81 annual TS testing revealed that the control room emergency
[0] [3] filtration system, common to both units, was not operating within TS,
[0] [4] Section 15.3.12.2.C, limits. Thus, the subject system was deemed in-
[0] [5] operable by TS definition. This condition placed the plant in a degraded
[0] [6] mode of operation allowed by the TS. The event had no effect on the
[0] [7] public health and safety as the system would have operated, although at
[0] [8] a lower than design flow rate, to filtrate the control room atmosphere.

[illegible]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The low system flowrates were caused by an improperly balanced backdraft
1 1 damper located at the W14A fan discharge and an improper setting of the
1 2 balancing damper located just upstream of the systems roughing filters.
1 3 The dampers were readjusted. The system was retested and found to per-
1 4 form satisfactorily and was returned to service on 5-20-81.

FACILITY STATUS				% POWER			OTHER STATUS (30)		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION (32)	
1	5	E	(28)	0	8	0	(29)	N/A	B	(31)	Tech. Spec. Testing	

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z 33 Z 34 N/A

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

N/A

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	N/A	(39)

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	N/A

1		2		3		4		5		6		7		8		9		10		11		12	
LOSS OF OR DAMAGE TO FACILITY (43)																							
TYPE		DESCRIPTION																					
1	9	Z	(42)	N/A																			

7 8 9 10

PUBLICITY

ISSUED DESCRIPTION (45)

2 0 N (44) N/A

NRC USE ONLY

10 DUP OF 8106162
NAME OF PREPARER C. W. Fay

PHONE: 414/277-2811

800-4-A-9278

ATTACHMENT TO LICENSEE EVENT REPORT NO. 81-005/03L-0

Wisconsin Electric Power Company
Point Beach Nuclear Plant Unit 1
Docket No. 50-266

On May 15, 1981, at 1100 hours, during Technical Specification ventilation system performance testing, it was discovered that the fans of the control room emergency filtration system, common to both units, were not operating within plus or minus 10 percent of their designed flow rates as required by Technical Specification, Section 15.3.12.2.C. Thus, the control room emergency filtration system was deemed inoperable by Technical Specification definition. This condition placed the plant in a degraded mode of operation allowed by the Technical Specifications.

The event had no effect on the public health and safety as the system would have operated to filter, although at a lower flowrate than originally designed, the control room atmosphere. In addition, the forced air breathing apparatus was available to the control room personnel to mitigate the consequences of airborne radioisotope contamination of the control room atmosphere.

The overall system flowrate was 3600 scfm while operating on fan W14A, and 4300 scfm while operating on fan W14B. The system design flowrate is 4950 scfm. The low system flowrate, while operating with fan W14A, was caused by an improperly balanced backdraft damper located just downstream of the fan discharge, and an improperly adjusted balancing damper located just upstream of the system's roughing filters. The low system flowrate, while operating with fan W14B, was caused by the improperly adjusted balancing damper located just upstream of the system's roughing filters.

The backdraft damper was rebalanced and the balancing damper was reset. The system was retested, and found to perform satisfactorily. The system was returned to service at 0700 hours on May 20, 1981.