

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | S | C | N | E | E | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 1 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

01 | 0 | 5 | 0 | 0 | 0 | 0 | 2 | 6 | 9 | 7 | 0 | 5 | 1 | 1 | 3 | 8 | 1 | 8 | 0 | 6 | 1 | 0 | 8 | 1 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | On May 13, 1981, a loss of valve position indication for CCW-8 was noticed.

03 | The valve was determined to be electrically inoperable. An operator was placed

04 | at the valve to manually operate CCW-8 if required. Thus, the health and

05 | safety of the public were not affected by this incident.

06 |

07 |

08 |

09 | SYSTEM CODE: C F 11 CAUSE CODE: X 12 CAUSE SUBCODE: Z 13 COMPONENT CODE: E L E C T R I C 14 COMB. SUBCODE: Z 15 VALVE SUBCODE: Z 16

17 | LER/NO REPORT NUMBER: 8 1 1 23 | SEQUENTIAL REPORT NO.: 0 0 8 24 | OCCURRENCE CODE: 0 1 25 | REPORT TYPE: T 26 | REVISION NO.: 0 27

ACTION: FUTURE ACTION: Z 19 EFFECT ON PLANT: Z 20 SHUTDOWN METHOD: Z 21 HOURS: 0 0 0 0 22 ATTACHMENT SUBMITTED: Y 23 APPROX. FORM SUB.: N 24 PRIME COMP. SUPPLIER: L 25 COMPONENT MANUFACTURER: 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The loss of CCW-8 valve automatic operability was caused by an open circuit in

11 | several conductors in the control cable. Immediate corrective action was to

12 | send an operator to the valve to verify operability. The control cable was

13 | replaced and the valve electrically cycled.

14 |

15 | FACILITY STATUS: E 28 % POWER: 0 0 29 OTHER STATUS: NA 30 METHOD OF DISCOVERY: A 31 DISCOVERY DESCRIPTION: Operator Observation 32

16 | ACTIVITY CONTENT RELEASED OR RELEASE: Z 33 AMOUNT OF ACTIVITY: NA 34 LOCATION OF RELEASE: NA 35

17 | PERSONNEL EXPOSURES: NUMBER: 0 0 0 37 TYPE: Z 38 DESCRIPTION: NA 39

18 | PERSONNEL INJURIES: NUMBER: 0 0 0 40 DESCRIPTION: NA 41

19 | LOSS OF OR DAMAGE TO FACILITY: TYPE: Z 42 DESCRIPTION: NA 43

20 | PUBLICITY: ISSUED DESCRIPTION: N 44 NRC USE ONLY