

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	S	I	C	N	E	E	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5			
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37			
CON'T		REPORT SOURCE		DOCKET NUMBER										EVENT DATE										REPORT DATE									

0	1	L	6	0	5	0	0	0	2	7	0	7	0	5	0	6	8	1	8	0	6	0	5	8	1	9				
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On May 6, 1981, the Unit 2 Turbine Driven Emergency Feedwater Pump (TDEFWP) oil sump was discovered empty. Both motor driven EFDW pumps were operable at the time that the TDEFDP pump was inoperable. The motor driven pumps would have started automatically on a loss of feedwater to provide the total amount of auxiliary feedwater flow required for removal of decay heat. The health and safety of the public was not jeopardized by this incident.

0	9	H	H	11	X	12	Z	13	P	U	M	P	X	X	14	B	15	Z	16		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26		
LIFE/REPORT NUMBER		EVENT YEAR		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE		COMP SUBCODE		VALVE SUBCODE		SEQUENCE REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.	
81		81		X		Z		P U M P X X		B		Z		012		03		L		0	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NRC FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER					
X		Z		Z		Z		0000		Y		N		L		G 0 8 0					

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

It is not known what caused the TDEFWP oil sump to be empty. When the TDEFWP oil sump was discovered empty, the pump control switch was placed in the "locked out" position to prevent an automatic start of the pump. The oil level of the tank was restored to normal within 47 minutes of the discovery. Procedure changes have been made to the Unit 1, 2 and 3 oil purifier operating procedures.

1	5	E	28	1	0	0	29	NA	30	A	31	Operator Observation	32
7	8	9	10	11	12	13	14	15	16	17	18	19	20
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION					
E		100		NA		A		Operator Observation					
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE							
Z		Z		NA		NA							
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION							
000		37		Z		NA							
PERSONNEL INJURIES		NUMBER		DESCRIPTION									
000		40		NA									
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION									
Z		42		NA									
PUBLICITY		ISSUED		DESCRIPTION									
Z		44		NA									

NAME OF PREPARER J. L. Jones

PHONE: (704) 373-8197

8107200350 810605
PDR ADDCK 05000270
S PDR