

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	1	5	7	0	6	0	9	8	1	8	0	7	0	7	8	1	9
60	61								68	69						74	75							80
DOCKET NUMBER											EVENT DATE							REPORT DATE						

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

7 8 9

SYSTEM CODE 11 CAUSE CODE 12 CAUSE SUBCODE 13 COMPONENT CODE 14 COMP. SUBCODE 15 VALVE SUBCODE 16

0 9 I D X Z I N S T R U X Z

9 10 11 12 13 14 15 16

(17) LER/RO REPORT NUMBER	EVENT YEAR 81 21 22	SEQUENTIAL REPORT NO. 018 23 24 25 26	OCCURRENCE CODE 03 27 28 29	REPORT TYPE L 30 31	REVISION NO. 0 32
ACTION TAKEN X 33	FUTURE ACTION Z 34	EFFECT ON PLANT Z 35	SHUTDOWN METHOD Z 36	HOURS 000 37 38 39	(22)
				ATTACHMENT SUBMITTED Y 40 41	(23)
				NPRD-4 FORM SUB Y 42	(24)
				PRIME COMP. SUPPLIER N 43	(25)
				COMPONENT MANUFACTURER W120 44 45 46 47	(26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 THE APPARENT CAUSE OF THE INCIDENT IS DUE TO MOMENTARY LOSS OF ALL AC TO THE DRAWER

1 1 CAUSING LOSS OF HIGH VOLTAGE. THIS IS INHERENT TO WESTINGHOUSE SOURCE RANGE HIGH

1 2 VOLTAGE SUPPLY CUTOUT CIRCUITS. THIS LOSS WAS DUE TO THE SWITCHING OF CRID #2 FROM

1 3 THE ALTERNATE TO NORMAL SOURCE, WHICH SUPPLIES AC POWER TO THE DRAWER. THE DRAWER

4 FUSES WERE REMOVED AND REINSTALLED WHICH RE-ESTABLISHED THE (SEE ATTACHED SUPPLEMENT)

7	8	9	FACILITY STATUS		% POWER		OTHER STATUS	(30)	METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	(32)	80
1	5	H	(28)		0	0	0	NA	B	(31)	OPERATOR OBSERVATION		80
7	8	9			10	11	12	13	44	45	46		80

ACTIVITY CONTENTY
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 Z (33) Z (34) NA NA

7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37) Z	(38) NA	(39)		

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	NA

1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72</																																																									

PUBLICITY
 ISSUED DESCRIPTION (45)
 2 0 N (44) NA
 8107210354 810707
 PDR ADDCK 05000315
 S PDR
 NRC USE ONLY

NRC USE ONLY

NAME OF PREPARER

R. A. PALMER

PHONE: 616-465-5901

FO 917-926

ATTACHMENT TO LER #81-018/03L-0 _____

SUPPLEMENT TO CAUSE DESCRIPTION

HIGH VOLTAGE AND THE SYSTEM WAS RETURNED TO SERVICE.