

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 G A E I H 2 2 J 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 17 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 3 6 6 7 0 6 2 2 8 1 8 0 7 0 9 8 1 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While operating at 2108 MWt HNP-2-1050, Surveillance Checks, was per-
0 3 formed. This procedure revealed a defective transmitter 2T48-N0101A in
0 4 the postaccident torus water level indicator 2T48-R622A. Plant operation
0 5 was not affected as a result of this event. The health and safety of
0 6 the public was not affected. This is a nonrepetitive event. A generic
0 7 review revealed that Unit 1 uses a different type of indicator.

0 8

0 9 SYSTEM CODE S A 11 CAUSE CODE E 12 CAUSE SUBCODE E 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE I 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 14 15 16
17 LER/RO REPORT NUMBER 18 19 EVENT YEAR 20 21 22 SEQUENTIAL REPORT NO. 23 24 25 26 OCCURRENCE CODE 27 28 29 REPORT TYPE 30 31 REVISION NO. 32
0 1 0 5 9 0 3 L 0
33 ACTION TAKEN 34 FUTURE ACTION 35 EFFECT ON PLANT 36 SHUTDOWN METHOD 37 HOURS 38 ATTACHMENT SUBMITTED 39 NPRD-4 FORM SUB. 40 PRIME COMP. SUPPLIER 41 COMPONENT MANUFACTURER
B 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 A 25 R 3 6 9 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of this event has been attributed to low fluid level in the
1 1 reference leg sensing line. MR 2-81-2723 was written to backfill the
1 2 low sensing line on the transmitter. The indicator was declared opera-
1 3 tive and returned to service.

1 4

1 5 FACILITY STATUS E 28 % POWER 0 8 6 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Inservice Inspection 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 6 ACTIVITY CONTENT Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

2 0 PUBLICITY ISSUED N 44 DESCRIPTION 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
8107210405 810709
PDR ADDCK 05000366
S PDR
NRC USE ONLY

LER #: 50-366/1981-059
Licensee: Georgia Power Company
Facility Name: Edwin I. Hatch
Docket #: 50-366

Narrative Report
for LER 50-366/1981-059

On 6-22-81, while operating at 86% power, HNP-2-1050, Daily Channel Surveillance Checks, was performed. This procedure revealed that the postaccident torus water level indicator 2T48-R622A was reading approximately 25 inches higher than the redundant indicator 2T48-R622B. The indicator was declared inoperative per Tech Specs section 3.3.6.4.a. This is a nonrepetitive event. The cause of this event has been attributed to low fluid level in the reference leg sensing line. MR 2-81-2723 was written to backfill the low sensing line on transmitter 2T48-N0101A. The indicator was declared operative and returned to service.

Plant operation was not affected as a result of this event. The health and safety of the public was not affected. A generic review revealed that Unit 1 uses a different type of indicator.