

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	N	M	N	P	1	0	0	-	0	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4	1	5
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35

0	1	L	0	5	0	0	0	2	6	3	7	0	6	1	7	8	1	8	0	7	1	6	8	1	9			
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal operations, while removing insulation, cracks were discovered on
0 3 | 4" and 1" RWCU heat exchanger piping, where they connect to the heat exchanger.
0 4 | This constituted a degradation of a system designed to carry radioactive material
0 5 | resulting from the fission process. Event reportable per T.S.6.7.B.2.d. No
0 6 | similar previous occurrences. This occurrence had no effect on public health
0 7 | and safety.

0	9	C	G	11	B	12	B	13	P	I	P	E	X	X	14	B	15	Z	16	17	8	1	0	1	7	0	3	L	0	18	X	19	Z	20	Z	21	0	0	0	0	22	N	23	Y	24	N	25	P	1	6	0	26
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50									

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Leak in 4" pipe is believed due to poor fit-up and welding. 3-inch slag line
1 1 | found near root of weld, which was removed and weld repaired. Crack in 1" pipe
1 2 | actually in 1" weld coupling that attaches to the heat exchanger. Failure analysis
1 3 | being performed. QA will inspect related piping during upcoming outage.

1	5	E	28	1	0	0	29	NA	30	A	31	Maintenance Observation	32
7	8	9	10	11	12	13	14	15	16	17	18	19	20

1	7	0	1	4	37	E	38	QC-4-1.6 REM, Eng.-1-.45 REM, pipe fitters-5-4.0 REM	39
7	8	9	10	11	12	13	14	15	16

1	9	Z	42	NA	43
7	8	9	10	11	12

2	0	N	44	NA	45
7	8	9	10	11	12

NAME OF PREPARER Patrick S. Thurman

PHONE: 612-295-5151

8107240178 810716
PDR ADOCK 05000263
S PDR