

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 I L D R S 3 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 37 CAT 58

CONT

01 REPORT SOURCE L 6 0 5 0 0 0 2 4 9 7 0 6 1 8 8 1 3 0 7 1 3 8 1 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While performing Isolation Condenser Steam/Condensate Line High Flow Calibration, found
03 switch 3-1349B actuated at 32.8 inches W.C. increasing in excess of T.S. Limit of 32
04 inches. This constitutes operation in a degraded condition (T.S. Table 3.2.1). Safety
05 significance was minimal, since redundant switch was available. No effect on public
06 health or safety. Previous occurrence R.O. 79-22/03L-0 Docket 50-249.

07
08
7 8 9 80

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
I C 11 F 12 E 13 I N S T R U 14 S 15 Z 16
9 10 1 12 13 18 19 20
17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
8 1 0 1 5 0 3 L 0
21 22 23 24 26 27 28 29 30 31 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
E 18 X 19 Z 20 Z 21 0 0 0 0 N 23 N 24 N 25 B 0 8 0 0 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Due to instrument drift flow switch made up contacts above limits. Completed DIP
11 010-9 and reset switch to trip at 29.1 inches water column increasing and verified
12 repeatability. Switches are tested monthly using DIS 1300-2.

13
14
7 8 9 80

15 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
E 28 0 9 8 29 N/A B 31 Instrument Surveillance
7 8 9 10 12 13 44 45 46 80

16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
Z 33 Z 34 N/A N/A
7 8 9 10 11 44 45 80

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
0 0 0 37 Z 38 N/A
7 8 9 11 12 13 30

18 PERSONNEL INJURIES NUMBER DESCRIPTION
0 0 0 40 N/A
7 8 9 11 12 30

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
Z 42 N/A
7 8 9 10 30

20 PUBLICITY ISSUED DESCRIPTION
N 44 N/A
7 8 9 10 30

21 PDR ADOCK 05000249
S PDR
7 8 9 10 30



Commonwealth Edison

DEVIATION REPORT

DVR NO.	STA	UNIT	YEAR	NO.
D-12-3	-81-	34		

PART 1 TITLE OF DEVIATION
Unit 3 Isolation Condenser Condensate Lin Hi Flow Switch Trips
Greater Than 32 Inches W.C.

OCCURRED
6/18/81 1400
DATE TIME

SYSTEM AFFECTED 1300
Isolation Condenser

PLANT CONDITIONS
MODE Run PWR(MWT) 2487 LOAD(MWE) 804

TESTING
☒ YES ☐ NO

DESCRIPTION OF EVENT

DIP 1300-2 on Unit 3 found dpis 3-1349B to trip at 32.8 inches W.C. increasing on first check.
(Second and third checks showed 33 inches W.C. increasing)

DESCRIPTION OF CAUSE

None found

OTHER APPLICABLE INFORMATION

Completed DIP 010-9 and reset switch to trip at 29.1 inches W.C. increasing and verified
repeatability.

EQUIPMENT ☐ YES
FAILURE ☒ NO

DR NO.

-

WR NO.

-

Alan R. Zapotocky

6/18/81

RESPONSIBLE SUPERVISOR

DATE

PART 2 OPERATING ENGINEERS COMMENTS

The switch was immediately rec librated and repeatability was verified.

TYPE OF DEVIATION
REPORTABLE OCCURRENCE

☐ 14 DAY ☐ 10CFR21

☒ 30 DAY NOTIFICATION
6.6.B.2.a

EVENT OF POTENTIAL
PUBLIC INTEREST

☐

TECH SPEC
VIOLATION

☐

NON-REPORTABLE
OCCURRENCE

☐

ANNUAL
REPORTING

YES ☒

NO ☐

SAFETY-
RELATED
WR ISSUED

YES ☐

NO ☒

REPORTABLE OCCURRENCE
NUMBER

81-15/03E-0

ACTION ITEM NO.

PROMPT ON-SITE NOTIFICATION

R. M. Ragan

6/19/81

11:30

TITLE

DATE

TIME

TITLE

DATE

TIME

24-HOUR NRC NOTIFICATION

☐ TPH

REGION III

DATE

TIME

☐ TGM

REGION III & DOL

DATE

TIME

PROMPT OFF-SITE NOTIFICATION

F. A. Falmer

6/19/81

12:38

TITLE

DATE

TIME

TITLE

DATE

TIME

RESPONSIBLE COMPANY OFFICER INFORMED OF 10CFR21
CONDITIONS AND THEIR REPORT TO NRC

TITLE

DATE

TIME

REVIEW AND COMPLETED

Michael Wright

6/19/81

OPERATING ENGINEER

DATE

ACCEPTANCE BY STATION REVIEW
AS REQUIRED

DATE

RESOLUTION APPROVED AND
AUTHORIZED FOR DISTRIBUTION

STATION SUPERINTENDENT

7/14/81
DATE