

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

July 9, 1981

JUL 13 AM 5:50

.. , James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNIT 2 - OFFICE OF INSPECTION AND ENFORCEMENT
BULLETIN 79-13, RII:JPO 50-328 - SUPPLEMENTAL REPORT

As required by IE Bulletin 79-13, Cracking in Feedwater System Piping, we have conducted post hot-functional inspections of the feedwater piping at Sequoyah Nuclear Plant unit 2.

A radiographic examination of all feedwater nozzle-to-pipe welds and adjacent pipe and nozzle areas has been completed on Sequoyah unit 2, and no unacceptable indications were found. A visual inspection of feedwater system piping supports and snubbers in containment has been completed, and three problems were identified. All three deficiencies were relatively minor and will be corrected before initial criticality.

If you have any questions, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

IE11
3
110

8107240293 810709
PDR ADOCK 05000328
Q PDR