

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M I P A L 1 2 0 0 - 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CONT
01 REPORT SOURCE L 6 0 5 0 0 0 2 5 5 7 0 6 2 6 8 1 8 0 7 1 6 8 1 9
7 8 9 60 61 COCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
02 During test start of 1-1 diesel generator, the engine failed to reach
03 rated speed (unit reached 58.5 hertz). T.S. 6.9.2.b2 and 3.7.2i apply.
04 Event had no effect on public health or safety. Refer to LER 81-25.
05
06
07
08
09

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE
E E A E N G I N E Z Z
9 10 11 12 13 14 15 16

17 LER-RO REPORT NUMBER 81
EVENT YEAR 81
SEQUENTIAL REPORT NO. 026
OCCURRENCE CODE 03
REPORT TYPE L
REVISION NO. 0

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
A Z Z Z 0000 N N A A 152
33 34 35 36 37 40 41 42 43 44 45

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10 Motor-driven potentiometer in engine speed control circuit experienced
11 a motor failure. Motor replacement corrected the problem.
12
13
14

FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
E 0000 NA C Test
7 8 9 10 11 12 13 44 45 46 80

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
Z Z NA NA
7 8 9 10 11 12 44 45 80

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
0000 NA
7 8 9 10 11 12 13 80

PERSONNEL INJURIES NUMBER DESCRIPTION (41)
0000 NA
7 8 9 10 11 12 13 80

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)
Z NA
7 8 9 10 11 12 80

PUBLICITY ISSUED DESCRIPTION (45)
N NA
7 8 9 10 11 12 80

NRC USE ONLY
58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80